



Hall County Regional Planning Commission

**Wednesday, October 5, 2022
Regular Meeting**

Item F4

Public Hearing – Proposed CRA Area #28- Grand Island Proposed CRA Area #28 located between 13th Street and State Street and U.S. Highway 281 and Webb Road (including the Conestoga Mall) in Grand Island, Hall County Nebraska). Resolution 2023-03 (C-04-23GI)

Staff Contact:

Agenda Item # 7

PLANNING DIRECTOR RECOMMENDATION TO REGIONAL PLANNING COMMISSION:

September 20, 2022

SUBJECT: *CRA Blight Study (Proposed CRA Area 28) C-04-23GI*

PROPOSAL: Attached is a copy of a Substandard and Blight Study as prepared by Marvin Planning Consultants entitled “Grand Island NE, Blighted and Substandard Study Area 28”. This area as defined by the study will be referred to as Community Redevelopment Authority (CRA) Area 28. The study as prepared and submitted indicates that this property could be considered substandard and blighted. This only includes property that is located within the municipal limits of Grand Island. The study as presented shows that this property meets the criteria to be declared blighted and substandard of its own accord. The Planning Commission recommendation must be forwarded to the Grand Island City Council within 30 days of making the recommendation.

OVERVIEW

This study is approximately 78.45 acres of property in northwest Grand Island located between U.S. Highway 281 and Webb Road and State and 13th Streets including the Conestoga Mall (Study Area).

The Statutory authority and direction to the Planning Commission is referenced below to explain the Planning Commission purpose in reviewing the study:

18-2109. Redevelopment plan; preparation; requirements; planning commission or board; public hearing; notice; governing body; public hearing; notice.

(1) An authority shall not prepare a redevelopment plan for a redevelopment project area unless the governing body of the city in which such area is located has, by resolution adopted after the public hearings required under this section, declared such area to be a substandard and blighted area in need of redevelopment.

(2) Prior to making such declaration, the governing body of the city shall conduct or cause to be conducted a study or an analysis on whether the area is substandard and blighted and shall submit the question of whether such area is substandard and blighted to the planning commission or board of the city for its review and recommendation. The planning commission or board shall hold a public hearing on the question after giving notice of the hearing as provided in section 18-2115.01. Such notice shall include a map of sufficient size to show the

area to be declared substandard and blighted or information on where to find such map and shall provide information on where to find copies of the substandard and blighted study or analysis conducted pursuant to this subsection. The planning commission or board shall submit its written recommendations to the governing body of the city within thirty days after the public hearing.

(3) Upon receipt of the recommendations of the planning commission or board, or if no recommendations are received within thirty days after the public hearing required under subsection (2) of this section, the governing body shall hold a public hearing on the question of whether the area is substandard and blighted after giving notice of the hearing as provided in section 18-2115.01. Such notice shall include a map of sufficient size to show the area to be declared substandard and blighted or information on where to find such map and shall provide information on where to find copies of the substandard and blighted study or analysis conducted pursuant to subsection (2) of this section. At the public hearing, all interested parties shall be afforded a reasonable opportunity to express their views respecting the proposed declaration. After such hearing, the governing body of the city may make its declaration.

(4) Copies of each substandard and blighted study or analysis conducted pursuant to subsection (2) of this section shall be posted on the city's public web site or made available for public inspection at a location designated by the city.

~Reissue Revised Statutes of Nebraska

The attached study does not include a redevelopment plan. If this study is approved subsequent action will be necessary by both the Planning Commission and the City Council prior to any action involving Tax Increment Financing or the expenditure of tax dollars from the CRA budget within this area.

It is appropriate for the planning commission in conducting its review and considering its recommendation regarding the substandard and blighted designation to:

1. review the study,
2. take testimony from interested parties,
3. make findings of fact, and
4. Include those findings of fact as part of its recommendation to Council.

Blighted and Substandard Defined

The terms blighted and substandard have very specific meanings within the context of the Community Redevelopment Statutes. Those terms as defined by Statute are included below:

Section 18-2103
Terms, defined.

For purposes of the Community Development Law, unless the context otherwise requires:

(3) Blighted area means an area (a) which, by reason of the presence of a substantial number of deteriorated or deteriorating structures, existence of defective or inadequate street layout, faulty lot layout in relation to size, adequacy, accessibility, or usefulness, insanitary or unsafe conditions, deterioration of site or other improvements, diversity of ownership, tax or special assessment delinquency exceeding the fair value of the land, defective or unusual conditions of title, improper subdivision or obsolete platting, or the existence of conditions which endanger life or property by fire and other causes, or any combination of such factors, substantially impairs or arrests the sound growth of the community, retards the provision of housing accommodations, or constitutes an economic or social liability and is detrimental to the public health, safety, morals, or welfare in its present condition and use and (b) in which there is at least one of the following conditions: (i) Unemployment in the designated area is at least one hundred twenty percent of the state or national average; (ii) the average age of the residential or commercial units in the area is at least forty years; (iii) more than half of the plotted and subdivided property in an area is unimproved land that has been within the city for forty years and has remained unimproved during that time; (iv) the per capita income of the area is lower than the average per capita income of the city or village in which the area is designated; or (v) the area has had either stable or decreasing population based on the last two decennial censuses. In no event shall a city of the metropolitan, primary, or first class designate more than thirty-five percent of the city as blighted, a city of the second class shall not designate an area larger than fifty percent of the city as blighted, and a village shall not designate an area larger than one hundred percent of the village as blighted. A redevelopment project involving a formerly used defense site as authorized under section 18-2123.01 shall not count towards the percentage limitations contained in this subdivision;

*(31) **Substandard areas** shall mean an area in which there is a predominance of buildings or improvements, whether nonresidential or residential in character, which, by reason of dilapidation, deterioration, age or obsolescence, inadequate provision for ventilation, light, air, sanitation, or open spaces, high density of population and overcrowding, or the existence of conditions which endanger life or property by fire and other causes, or any combination of such factors, is conducive to ill health, transmission of disease, infant mortality, juvenile delinquency, and crime, (which cannot be remedied through construction of prisons), and is detrimental to the public health, safety, morals, or welfare;*

~Reissue Revised Statutes of Nebraska

ANALYSIS-Blight and Substandard Study

The following findings are copied directly from the Study. The analysis of the substandard and blighted factors is conducted on pages 7 to 23 of the study.

FINDINGS FOR GRAND ISLAND

Study Area 28 has several items contributing to the Blight and Substandard Conditions. These conditions include:

Blighting Summary

These conditions are contributing to the blighted conditions of the study area.

Criteria under Part A of the Blight Definition

- **Substantial number of deteriorating structures**
 - Within the study are 80.0% of the structures were deemed to be in either average or badly worn condition.
 - Several locations around the primary mall are indicating moisture damage to the brick façade. There is clear moisture damage inside of the mall as well.
- **Deterioration of site or other improvements**
 - The majority of the asphalt parking areas around the primary mall is in a deteriorating state and appears to have forgone updating for a considerable time.
 - There are several places where the parking surfaces are in a worse than deteriorated state based upon the photographs in the report.
- **Diversity of Ownership**
 - There are 13 different property owners within the study area.
 - The majority of the buildings owned by corporations, sit on top of ground owned by another party, typically, Conestoga Realty or Conestoga North.
- **Improper Subdivision or Obsolete Platting**
 - First and foremost are the private streets on the north side of the study area, Conestoga Drive and Overland Road.
 - The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
 - The positioning of lots along West State Street and North Webb Road have access drives in a manner that makes traffic control and congestion problematic.
- **Faulty Lot Layout**
 - The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
 - The positioning of lots along West State Street and North Webb Road have access drives in a manner making traffic control and congestion problematic.
- **Combination of factors which are impairing and/or arresting sound growth**
 - Functional Obsolescence is a contributing factor to sound growth
 - Retail markets of the 21st Century are impairing growth of the area
 - The buildup of the outlots of the mall area
- **Defective/Inadequate street layouts**
 - The layout of the primary and secondary thoroughfares on site are in conflict with key functional areas such as deliveries and loading docks
 - The two primary streets entering the mall property from the north are private streets
 - There are several points along the outer travel route that comes into conflict with secondary travel paths.
- **Insanitary and Unsafe Conditions**
 - The Conestoga Mall portion of the study area was tested for the presence of asbestos and the report filed in August 2022 indicated mitigatable levels of asbestos present throughout the facility

- **Dangerous conditions to life or property due to fire or other causes**
 - The Conestoga Mall portion of the study area was tested for the presence of asbestos and the report filed in August 2022 indicated mitigatable levels of asbestos present throughout the facility

Criteria under Part B of the Blight Definition

- **The average age of the residential or commercial units in the area is at least forty years**
 - 28 (80.0%) buildings or improvements were determined to be 40 years of age or older
 - 7 (20.0%) buildings or improvements were determined to be less than 40 years of age
 - The average age based upon a cumulative age calculation is 41.8 years.
 - 94.3% of the built square footage in the study area is 40 years of age or older.
- **Stable or decreasing population based upon the last two decennial census**
 - The study area has had a stable or decreasing population over the last two decennial census.

The other criteria for Blight were not present in the area, these included:

- Tax or special assessment delinquency exceeding fair value of the land.
- Defective or unusual condition of title,
- Unemployment in the designated area is at least 120% of the state or national average.
- The per capita income of the area is lower than the average per capita income of the city or village in which the area is designated.

These issues were either not present or were limited enough as to have little impact on the overall condition of the study area.

Substandard Summary

Nebraska State Statute requires that "...an area in which there is a predominance of buildings or improvements, whether nonresidential or residential in character, which, by reason of dilapidation, deterioration, **age** or obsolescence, inadequate provision for ventilation, light, air, sanitation, or open spaces, high density of population and overcrowding, or the existence of conditions which endanger life or property by fire and other causes, or any combination of such factors, is conducive to ill health, transmission of disease, infant mortality, juvenile delinquency, and crime, (which cannot be remedied through construction of prisons), and is detrimental to the public health, safety, morals, or welfare;"

This Study Area in Grand Island meets the definition of Substandard as defined in the Revised Nebraska State Statutes.

FINDINGS FOR GRAND ISLAND BLIGHT STUDY AREA #28

Blight Study Area #28 has several items contributing to the Blight and Substandard Conditions. These conditions include:

Blighted Conditions under Part A

- **Substantial number of deteriorating structures**
- **Deterioration of site or other improvements**
- **Diversity of Ownership**
- **Improper Subdivision or Obsolete Platting**
- **Faulty Lot Layout**

- Combination of factors which are impairing and/or arresting sound growth
- Defective/Inadequate street layouts
- Insanitary and Unsafe Conditions
- Dangerous conditions to life or property due to fire or other causes

Criteria under Part B of the Blight Definition

- The average age of the residential or commercial units in the area is at least forty years
- Stable or decreasing population based upon the last two decennial census

Substandard Conditions

- Average age of the structures in the area is at least forty years

RECOMMENDATION:

Blight and Substandard Designation

Planning Commission staff is recommending consideration of the following questions as a starting point in the analysis of this Study and in making a recommendation on the question of whether the property in question is blighted and substandard.

Recommend Questions for Planning Commission

- Does this property meet the statutory requirements to be considered blighted and substandard? (See the prior statutory references.)
- Are the blighted and substandard factors distributed throughout the Redevelopment Area, so basically good areas are not arbitrarily found to be substandard and blighted simply because of proximity to areas which are substandard and blighted? Is development of adjacent property necessary to eliminate blighted and substandard conditions in the area?
- Is public intervention appropriate and/or necessary for the redevelopment of the area?
- Will a blight declaration increase the likelihood of development/redevelopment in the near future and is that in the best interest of the City?
- What is the policy of the City toward increasing development and redevelopment in this area of the City?

Findings of fact must be based on the study and testimony presented including all written material and staff reports. The recommendation must be based on the declaration, not based on any proposed uses of the site. All of the testimony, a copy of the study and this memo along with any other information presented at the hearing should be entered into the record of the hearing.

If the Regional Planning Commission concludes that the area in question meets the definition of blighted and substandard and supports such conclusion with findings of fact they should move to recommend **approval** of the declaration as blighted and substandard based on the facts presented and identified at this meeting.

If the Regional Planning Commission concludes that the area in question does not meet the definition of blighted and substandard and supports such conclusions with findings of fact,

they should move to recommend **denial** of the declaration as blighted and substandard based on the facts identified.

_____ Chad Nabity AICP, Planning Director



Grand Island, Nebraska
Blight and Substandard Study - Area 28
Prepared for: Tunnel Wash I LLC



PURPOSE OF THE BLIGHT AND SUBSTANDARD STUDY

The purpose of completing this Blight and Substandard study is to examine existing conditions within a specific part of Grand Island. Woodsonia Acquistitions, LLC commissioned the study to analyze the possibility of declaring the area as blighted and substandard.

The City of Grand Island, when considering conditions of Blight and Substandard, look at those issues and definitions provided for in the Nebraska Community Redevelopment Law as found in Chapter 18, Section 2104 of the Revised Nebraska State Statutes, as follows:

"The governing body of a city, to the greatest extent it deems to be feasible in carrying out the provisions of the Community Development Law, shall afford maximum opportunity, consistent with the sound needs of the city as a whole, to the rehabilitation or redevelopment of the community redevelopment area by private enterprises. The governing body of a city shall give consideration to this objective in exercising its powers under the Community Development Law, including the formulation of a workable program, the approval of community redevelopment plans consistent with the general plan for the development of the city, the exercise of its zoning powers, the enforcement of other laws, codes, and regulations, relating to the use of land and the use and occupancy of buildings and improvements, the disposition of any property acquired, and the providing of necessary public improvements."

The Nebraska Revised Statutes §18-2105 continues by granting authority to the governing body for the formulation of a workable program; disaster assistance; effect. The statute reads,

"The governing body of a city or an authority at its direction for the purposes of the Community Development Law may formulate for the entire municipality a workable program for utilizing appropriate private and public resources to eliminate or prevent the development or spread of urban blight, to encourage needed urban rehabilitation, to provide for the redevelopment of substandard and blighted areas, or to undertake such of the aforesaid activities or other feasible municipal activities as may be suitably employed to achieve the objectives of such workable program. Such workable program may include, without limitation, provision for the prevention of the spread of blight into areas of the municipality which are free from blight through diligent enforcement of housing, zoning, and occupancy controls and standards; the rehabilitation or conservation of substandard and blighted areas or portions thereof by replanning, removing congestion, providing parks, playgrounds, and other public improvements by encouraging voluntary rehabilitation and by compelling the repair and rehabilitation of deteriorated or deteriorating structures; and the clearance and redevelopment of substandard and blighted areas or portions thereof."

"Notwithstanding any other provisions of the Community Development Law, where the local governing body certifies that an area is in need of redevelopment or rehabilitation as a result of flood, fire, hurricane, earthquake, storm, or other catastrophe respecting which the Governor of the state has certified the need for disaster assistance under federal law, the local governing body may approve a redevelopment plan and a redevelopment project with respect to such area without regard to the provisions of the Community Development Law requiring a general plan for the municipality and notice and public hearing or findings other than herein set forth."

Based on the Nebraska Revised Statutes §18-2103 the following definitions shall apply:

"Blighted area" means an area (a) which, by reason of the presence of a substantial number of deteriorated or deteriorating structures, existence of defective or inadequate street layout, faulty lot layout in relation to size, adequacy, accessibility, or usefulness, insanitary or unsafe conditions, deterioration of site or other improvements, diversity of ownership, tax or special assessment delinquency exceeding the fair value of the land, defective or unusual conditions of title, improper subdivision or obsolete platting, or the existence of conditions which endanger life or

property by fire and other causes, or any combination of such factors, substantially impairs or arrests the sound growth of the community, retards the provision of housing accommodations, or constitutes an economic or social liability and is detrimental to the public health, safety, morals, or welfare in its present condition and use and (b) in which there is at least one of the following conditions: (i) Unemployment in the designated area is at least one hundred twenty percent of the state or national average; (ii) the average age of the residential or commercial units in the area is at least forty years; (iii) more than half of the plotted and subdivided property in an area is unimproved land that has been within the city for forty years and has remained unimproved during that time; (iv) the per capita income of the area is lower than the average per capita income of the city or village in which the area is designated; or (v) the area has had either stable or decreasing population based on the last two decennial censuses. In no event shall a city of the metropolitan, primary, or first class designate more than thirty-five percent of the city as blighted, a city of the second class shall not designate an area larger than fifty percent of the city as blighted, and a village shall not designate an area larger than one hundred percent of the village as blighted. A redevelopment project involving a formerly used defense site as authorized under section 18-2123.01 shall not count towards the percentage limitations contained in this subdivision;"

"Extremely blighted area means a substandard and blighted area in which: (a) The average rate of unemployment in the area during the period covered by the most recent federal decennial census is at least two hundred percent of the average rate of unemployment in the state during the same period; and (b) the average poverty rate in the area exceeds twenty percent for the total federal census tract or tracts or federal census block group or block groups in the area;"

"Substandard area means an area in which there is a predominance of buildings or improvements, whether nonresidential or residential in character, which, by reason of dilapidation, deterioration, age or obsolescence, inadequate provision for ventilation, light, air, sanitation, or open spaces, high density of population and overcrowding, or the existence of conditions which endanger life or property by fire and other causes, or any combination of such factors, is conducive to ill health, transmission of disease, infant mortality, juvenile delinquency, and crime, (which cannot be remedied through construction of prisons), and is detrimental to the public health, safety, morals, or welfare; and"

"Workforce housing means:

- (a) Housing that meets the needs of today's working families;
- (b) Housing that is attractive to new residents considering relocation to a rural community;
- (c) Owner-occupied housing units that cost not more than two hundred seventy-five thousand dollars to construct or rental housing units that cost not more than two hundred thousand dollars per unit to construct. For purposes of this subdivision (c), housing unit costs shall be updated annually by the Department of Economic Development based upon the most recent increase or decrease in the Producer Price Index for all commodities, published by the United States Department of Labor, Bureau of Labor Statistics;
- (d) Owner-occupied and rental housing units for which the cost to substantially rehabilitate exceeds fifty percent of a unit's assessed value; and
- (e) Upper-story housing."

This Blight and Substandard Study is Blighted and Substandard Area 28. The Study is intended to give the Grand Island Community Redevelopment Authority, Hall County Regional Planning Commission and Grand Island City Council the basis for identifying and declaring Blighted and Substandard conditions are existing within the City's jurisdiction and as allowed under Chapter 18. Through this process, the City and property owners will attempt to address economic and/or social liabilities which are harmful to the well-being of the entire community.

Figure 1 shows the study area of this report. A Redevelopment Plan to be submitted in the future containing, by law, definite local objectives regarding appropriate land uses, improved traffic, public transportation, public utilities, and other public improvements, and the proposed land uses and building requirements in the redevelopment area and shall include:

- The boundaries defining the blighted and substandard areas in question (including existing uses and conditions of the property within the area), and
- A list of the conditions present, which qualify the area as blighted and substandard.

Through the redevelopment process, the City of Grand Island can guide future development and redevelopment throughout the area. The use of the Community Redevelopment Act by the City of Grand Island is intended to redevelop and improve the area. Using the Community Redevelopment Act, the City of Grand Island can assist in the elimination of negative conditions and implement different programs/projects identified for the City.

BLIGHT AND SUBSTANDARD ELIGIBILITY STUDY

This study targets a specific area within an established part of the community for evaluation. The area indicated in Figure 1 of this report. The findings are presented in the coming pages of the report.

Study Area

The following is the description of the designated area within Grand Island.

Point of beginning is the intersection of the centerlines of US Highway 281 and West State Street; thence bearing easterly along the centerline of West State Street to the intersection of the centerline of North Webb Road; thence, southerly along the centerline of North Webb Road to the intersection with the centerline of West 13th Street; thence, westerly along the centerline of West 13th Street to the intersection with the centerline of US Highway 281; thence, northerly along the centerline of US Highway 281 to the point of beginning.

EXISTING LAND USES

The term “Land Use” refers to the developed uses in place within a building or on a specific parcel of land. The number and type of uses are constantly changing within a community and produce some impacts either benefitting or detracting from the community. Existing patterns of land use are often fixed in older communities and neighborhoods, while development in newer areas is often reflective of current development practices.

The study area is within a highly commercial part of Grand Island. There are commercial uses to all sides of the study, including the redeveloping area of Blight and Substandard Area 9 from 2012.

Existing Land Use Analysis within Study Area

As part of the planning process, a survey conducted through both in-field observations, as well as data collection online using the Hall County Assessors website. This survey noted the use of each parcel of land within the study area. These data from the survey are found in the following paragraphs.

TABLE 1: EXISTING LAND USE, GRAND ISLAND - 2022

Type of Use	Acres	Percent of Developed land within the Study Area	Percent of Study Area
Residential	0	0.0%	0.0%
Single-family	0	0.0%	0.0%
Multi-family	0	0.0%	0.0%
Manufactured Housing	0	0.0%	0.0%
Commercial	63.45	87.3%	80.9%
Industrial	0	0.0%	0.0%
Quasi-Public/Public	0	0.0%	0.0%
Parks/Recreation	0	0.0%	0.0%
Transportation	9.22	12.7%	11.7%
Total Developed Land	72.67	100.0%	-
Vacant/Agriculture	5.78		7.4%
Total Area	78.45		100.0%


Source: Marvin Planning Consultants 2022

Table 1 includes the existing land uses for the entire study area. The table contains the total acres determined per land use from the survey; next is the percentage of those areas compared to the total developed land; and finally, the third set of data compare all land uses to the total area within the Study Area. The Study Area is made up of Commercial (80.9%), Open Space (7.4%), and Transportation oriented land (street and R.O.W; 11.7%). The entire area is considered completely developed.

Figure 1
Study Area Map



Figure 2
Existing Land Use Map



FINDINGS OF BLIGHT AND SUBSTANDARD CONDITIONS ELIGIBILITY STUDY

This section of the study examines the conditions found within the study area. The Findings Section reviews the conditions based upon the statutory definitions.

CONTRIBUTING FACTORS UNDER PART A OF THE BLIGHT DEFINITION

There were some conditions examined and evaluated in the field and online. Some conditions are reviewed in detail, on the following pages, while some of the statutory conditions are not present.

Structural Conditions

Existing structural conditions of buildings in the study area were determined using the Hall County Assessor's database. Structures rated out as either Very Good, Good, Fair, Average, or badly worn. Based upon the data provided to the planning team, the following is the breakdown for structures in the study area:

- 2 (5.7%) structures rated as very good
- 5 (14.3%) structures rated as good
- 0 (0.0%) structure rated as fair
- 28 (80.0%) structures rated as average
- 0 (0.0%) structures rated as badly worn



The exterior portion of the mall is showing considerable wear, likely due to deferred maintenance. In the photos on the previous page, there are examples of where masonry and wood construction has been compromised and is in danger of falling from the building onto the ground. Based upon a visual ground inspection, it appears like there is considerable water penetration in the brick-and-mortar system. Said photos also show water penetration inside one of the structures. An assumption was made, based upon the data, that an average condition or less would constitute less than desirable conditions due to age and condition of the structure/building. It is common for older structures to get more maintenance and upkeep to maintain a good or higher condition. Even an average structure shows some signs of deteriorating which in turn can become a dilapidated structure in the future if not maintained. Overall, 80.0% of the structures in this study area are an average condition or worse.

Due to the stated conditions found in the Hall County Assessor's data, the condition of the structures is a contributing factor.

Deterioration of Site or Other Improvements

Site Improvements Conditions

The site improvements include the areas determined to be common areas for public ingress and egress to the study area as well as the area designed to move vehicular traffic through the site. Also, this includes the actual surface parking areas. The condition of the site improvements varies greatly. The Study Area contains a major deteriorated condition; the parking areas throughout the area, as well as the demarcated driving areas. The parking areas throughout the entire Study Area are in a serious state of deterioration. They are not yet in a dilapidated condition. The parking surface and driving areas contain major surface cracking, small break-ups and spawling. These conditions have been likely caused by several circumstances over the years, including:

- Lack of maintenance
- Sub-soil conditions
- Heavier than expected traffic
- Freeze/thaw cycles

Preventing a number of these items are possible through proper design, enforcement, and maintenance, with maintenance being a key. Photos below indicate examples of different deteriorated conditions within the parking and driving areas across the entire site. Due to a large amount of broken pavement in the Study Area, the parking areas are considered to be deteriorated or in a state of deteriorating; therefore, they are a direct contributing factor to the conditions of blight.



Diversity of Ownership

Throughout the study area, there are 13 different property owners. However, in most cases, the difference is that one company owns the structure on the site; while, another entity, usually, Conestoga North or Conestoga Realty owns the ground underneath the structure. This creates potential issues with future redevelopment of structures and property if the different ownership groups disagree. Also, the fact structures sit on land owned by another party will create a potential detriment to future redevelopment. Due to this factor, it may be necessary for a public intervention to guide future redevelopment activities in this specific study area. Based upon the analysis, sufficient ownership issues present to make Diversity of Ownership a contributing factor for Blighting.

Improper Subdivision or Obsolete Platting

Improper Subdivision or Obsolete Platting is present in several ways. These factors are bulleted below:

- First and foremost are the private streets on the north side of the study area, Conestoga Drive and Overland Road.
- The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
- The positioning of lots along West State Street and North Webb Road have access drives in a manner that makes traffic control and congestion problematic.

See Figure 5 for specific locations of the discussed items above. Based upon the analysis, sufficient ownership issues present to make Improper Subdivision or Obsolete Platting a contributing factor for Blighting.

Faulty Lot Layout

Similar to Improper Subdivision or Obsolete Platting, Faulty Lot Layout is present in similar ways. These factors are bulleted below:

- The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
- The positioning of lots along West State Street and North Webb Road have access drives in a manner making traffic control and congestion problematic.

See Figure 6 for specific locations of the discussed items above. Based upon the analysis, sufficient ownership issues present to make Faulty Lot Layout a contributing factor for Blighting.

Combination of factors which are impairing and/or arresting sound growth

There are several factors present within the study area meeting this criterion are discussed in the following paragraphs.

Functional Obsolescence

The primary structure within the study area is the Conestoga Mall. The mall was constructed in the mid-1970's and was designed using common mall layouts and concepts. However, as the retail markets have been changing, these types of facilities have been losing popularity. It is a similar issue seen by the Grand Island Mall which was declared Blighted and Substandard in 2012 and has been the focus of several redevelopment projects since the declaration.

Malls and retail use constructed in today's economy are more open air, even in colder climate regions. The newer mall models are doing more to make the shopping experience more than "just shopping." These older regional malls have lost favor with consumers across the United States. Some examples within the region include the Imperial Mall in Hastings, the mall in North Platte, the mall in Hutchinson, KS. The phenomena have also affected larger cities such as Omaha; Kansas City, MO; Overland Park, KS; and more.

The survival of this mall into the future will be dependent on ownership willingness to re-focus the mall itself.

Figure 3
Structural Conditions



Figure 4
Deterioration of Site





Figure 5
Improper Platting



Retail Markets of the 21st Century

Retail in the 21st Century has been evolving rapidly. The evolution led by consumers wanting more than the 1960 to 1970 malls with their shopping experience has been a big factor; however, the rise of e-commerce and Amazon has also been a major contributing factor to the retail revolution.

With the retail revolution of the 21st Century, several mainstream retailers have had trouble competing. The major tenants of Sears, Yonkers, and JC Penneys have all vacated their spaces at the Conestoga Mall. Yonkers left in 2015, while the other two left shortly after. Sears filed for Chapter 11 bankruptcy protection, and closed February 2019. All three tenants left behind empty boxes, merchandise, and storage equipment in the spaces. A lack of major retailers located at Conestoga Mall impairs and arrests sound growth of this facility in the future.

The buildup of the mall area

Looking at the Conestoga Mall on aerials, the mall is located on the southernmost location of the land. North of the primary mall was eventual built-out with smaller strip centers. These strip centers to the north impair the future expansion of the primary mall. Also, the location of the primary mall and strip centers creates an issue with expanding parking on the mall property. These factors do impair and arrest sound growth of the study area.




Defective/Inadequate Street Layouts

Under normal blight evaluation, this criteria would apply to public streets. However, in the case of this study area, it applies to the internal traffic circulation of the mall property and the adjoining strip centers to the north. Figure 8 indicates the primary and secondary circulation loops. The Figure also indicates potential concerns with the layouts on the site. There are enough circulation concerns on-site to make Defective/Inadequate Street Layouts a contributing factor to declaring the area as Blighted.

INSANITARY AND UNSAFE CONDITIONS

Woodsonia commissioned an asbestos analysis of the Conestoga Mall portion of the study area. The study was completed by Heartland Testing and Consulting LLC in August 2022. The following areas for the mall were reviewed and/or sampled. Inspection of the following occupied spaces were not completed due to no access: Units 3A, 4, 7A, 9, 23B, 33, 34, 38 & 40. Inspection of sub-flooring in the occupied tenant spaces of the facility were limited due to current sales area floor coverings. Additional review of the occupied spaces sales are sub-floors should be completed when the spaces are available for destructive review. Below is a summary of the spaces with limited review: 8, 9, 10, 12, 13, 17, 19, 20, 23A, 24, 30, 31, 36, 37, 39A, 40A, 41, 42, 44, 49, 50, 52, 54, 58, 59, 60, 62, Best Buy and Dillard's.

Figure 7
Sample Area Diagram



Source: Heartlan Testing Report 2022

The findings of the study found the following:

- Sample SR-2 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-4 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-8 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- **Sample C-2 – Drywall Joint Compound contains 0.5% chrysotile asbestos.**
- Sample C-8 – Ceiling Texture contains 10% chrysotile asbestos.
- Sample C-11 – Ceiling Texture contains 10% chrysotile asbestos. Sample Y-4 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample Y-10 – 12"x12" Tile contains 3% chrysotile asbestos.
- Sample 8B-1 – Black Mastic contains 4% chrysotile asbestos.
- Sample 41-1 – 12"x12" Tile contains 3% chrysotile asbestos. Sample 41-1 – Black Mastic contains 5% chrysotile asbestos.
- Sample 48-1 – Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample 48-2 – Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample JC-4 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample JC-8 – Black/Yellow Mastic contains 2% chrysotile asbestos.
- Sample JC-9 – Black Mastic contains 4% chrysotile asbestos.

- Sample JC-10 – Silver/Black HVAC Sealant contains 6% chrysotile asbestos.
- Sample D-1 – Black mastic contains 5% chrysotile asbestos.
- Sample SRR-2 – Gray/Black Roof Patch contains 3% chrysotile asbestos.
- Assumed – Transite Panels at skylight soffit areas.

Based upon information in the report, all but one (highlighted in yellow) of the sample areas require mitigation of the materials by a State of Nebraska certified asbestos contract prior to renovation or demolition activities. Additional information regarding the study findings can be seen in the complete study attached to this report.

Therefore, based upon the findings of this asbestos study, the asbestos is a contributing factor to insanitary and unsafe conditions of the study area.

DANGEROUS CONDITIONS TO LIFE OR PROPERTY DUE TO FIRE OR OTHER CAUSES

Woodsonia commissioned an asbestos analysis of the Conestoga Mall portion of the study area. The study was completed by Heartland Testing and Consulting LLC in August 2022. The following areas for the mall were reviewed and/or sampled. Inspection of the following occupied spaces were not completed due to no access: Units 3A, 4, 7A, 9, 23B, 33, 34, 38 & 40. Inspection of sub-flooring in the occupied tenant spaces of the facility were limited due to current sales area floor coverings. Additional review of the occupied spaces sales are sub-floors should be completed when the spaces are available for destructive review. Below is a summary of the spaces with limited review: 8, 9, 10, 12, 13, 17, 19, 20, 23A, 24, 30, 31, 36, 37, 39A, 40A, 41, 42, 44, 49, 50, 52, 54, 58, 59, 60, 62, Best Buy and Dillard's, see Figure 7.

The findings of the study found the following:

- Sample SR-2 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-4 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-8 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample C-2 – Drywall Joint Compound contains 0.5% chrysotile asbestos.
- Sample C-8 – Ceiling Texture contains 10% chrysotile asbestos.
- Sample C-11 – Ceiling Texture contains 10% chrysotile asbestos. Sample Y-4 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample Y-10 - 12"x12" Tile contains 3% chrysotile asbestos.
- Sample 8B-1 – Black Mastic contains 4% chrysotile asbestos.
- Sample 41-1 – 12"x12" Tile contains 3% chrysotile asbestos. Sample 41-1 – Black Mastic contains 5% chrysotile asbestos.
- Sample 48-1 – Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample 48-2 - Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample JC-4 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample JC-8 – Black/Yellow Mastic contains 2% chrysotile asbestos.
- Sample JC-9 – Black Mastic contains 4% chrysotile asbestos.
- Sample JC-10 – Silver/Black HVAC Sealant contains 6% chrysotile asbestos.
- Sample D-1 – Black mastic contains 5% chrysotile asbestos.
- Sample SRR-2 – Gray/Black Roof Patch contains 3% chrysotile asbestos.
- Assumed – Transite Panels at skylight soffit areas.

Based upon information in the report, all but one (highlighted in yellow) of the sample areas require mitigation of the materials by a State of Nebraska certified asbestos contract prior to renovation or demolition activities. Additional information regarding the study findings can be seen in the complete study attached to this report.

Therefore, based upon the findings of this asbestos study, the asbestos is a contributing factor to dangerous conditions to life or property due to fire or other causes within the study area.

CONTRIBUTING FACTORS UNDER PART B OF THE BLIGHT DEFINITION

There were some conditions examined and evaluated in the field and online. Some conditions will be reviewed in detail, on the following pages, while some of the statutory conditions are not present.

Age of Structure

Age of structures can be a contributing factor to the blighted and substandard conditions in an area. Statutes allow for a predominance of structures 40 years of age or older to be a contributing factor regardless of their condition. The following paragraphs document the structural age of the structures within the Study Area. Note the age of structure was determined from the Appraisal data within the Hall County Assessor's website data.

TABLE 2: AVERAGE STRUCTURAL AGE, BY METHOD - 2018

Number	Year Built	Age	Cumulative Age	Running Total
1	1960	62	62	62
1	1970	52	52	114
15	1974	48	720	834
4	1975	47	188	1,022
1	1976	46	46	1,068
2	1978	44	88	1,156
1	1979	43	43	1,199
1	1980	42	42	1,241
2	1981	41	82	1,323
1	1989	33	33	1,356
3	1993	29	87	1,443
1	1995	27	27	1,470
2	1996	26	52	1,522
1	1998	24	24	1,546
1	2007	15	15	1,561
1	2021	1	1	1,562
35			Average	41.8

Source: Hall County Assessor's and Marvin Planning Consultants 2022

Another method to analyze this area is using square footage. State statute discusses commercial units; in the commercial world, it is not about the building as much as it is about square footage. Therefore, this analysis is also examining the age of the built square footage. Based upon data from the Hall County Assessor's office, there is a total of 647,019 built square footage in the area. Of the 647,019 total square footage, 610,089 built square feet are 40 years or older, which is 94.3% of the total build out. Therefore, more than 50% of the square footage is 40 years of age or older.

Figure 8
Defective Street Layout



Figure 9
Structure Age



The final means to examine the age of structures is the actual number of structures within the 40 years or more or less than 40 years categories. Overall, there are 35 structures within the study area, based upon the Hall County Assessor's data (Hall County Assessor divides the primary mall structure into 11 separate units, thus 35 total). After researching the structural age on the Hall County Assessor's and Treasurer's websites, the following breakdown was determined:

- 28 (80.0%) unit were determined to be 40 years of age or older
- 7 (20.0%) unit were determined to be less than 40 years of age

However, when examining the age based upon a cumulative approach, as in Table 2, the average age of the primary structures is equal to 41.8 years; thus, meeting the requirements of the statutes.

The age of the structures would be a direct contributing factor.

Stable or decreasing population based upon the last two decennial census

The population of the study area has seen a stable population based upon the last two decennial census'. Over the course of the past 40 years there have not been any residential units within this study area.

Therefore, stable or decreasing population based upon the last two decennial censuses is a contributing factor to the blighted conditions of the area.

These conditions are contributing to the blighted conditions of the study area.

Criteria under Part A of the Blight Definition

- **Substantial number of deteriorating structures**
 - Within the study are 80.0% of the structures were deemed to be in either average or badly worn condition.
 - Several locations around the primary mall are indicating moisture damage to the brick façade. There is clear moisture damage inside of the mall as well.
- **Deterioration of site or other improvements**
 - The majority of the asphalt parking areas around the primary mall is in a deteriorating state and appears to have forgone updating for a considerable time.
 - There are several places where the parking surfaces are in a worse than deteriorated state based upon the photographs in the report.
- **Diversity of Ownership**
 - There are 13 different property owners within the study area.
 - The majority of the buildings owned by corporations, sit on top of ground owned by another party, typically, Conestoga Realty or Conestoga North.
- **Improper Subdivision or Obsolete Platting**
 - First and foremost are the private streets on the north side of the study area, Conestoga Drive and Overland Road.
 - The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
 - The positioning of lots along West State Street and North Webb Road have access drives in a manner that makes traffic control and congestion problematic.
- **Faulty Lot Layout**
 - The developed area in the northeast corner of the study area has been built out in a clustered manner, making traffic circulation difficult.
 - The positioning of lots along West State Street and North Webb Road have access drives in a manner making traffic control and congestion problematic.

- **Combination of factors which are impairing and/or arresting sound growth**
 - Functional Obsolescence is a contributing factor to sound growth
 - Retail markets of the 21st Century are impairing growth of the area
 - The buildup of the outlots of the mall area
- **Defective/Inadequate street layouts**
 - The layout of the primary and secondary thoroughfares on site are in conflict with key functional areas such as deliveries and loading docks
 - The two primary streets entering the mall property from the north are private streets
 - There are several points along the outer travel route that comes into conflict with secondary travel paths.
- **Insanitary and Unsafe Conditions**
 - The Conestoga Mall portion of the study area was tested for the presence of asbestos and the report filed in August 2022 indicated mitigatable levels of asbestos present throughout the facility
- **Dangerous conditions to life or property due to fire or other causes**
 - The Conestoga Mall portion of the study area was tested for the presence of asbestos and the report filed in August 2022 indicated mitigatable levels of asbestos present throughout the facility

Criteria under Part B of the Blight Definition

- **The average age of the residential or commercial units in the area is at least forty years**
 - 28 (80.0%) buildings or improvements were determined to be 40 years of age or older
 - 7 (20.0%) buildings or improvements were determined to be less than 40 years of age
 - The average age based upon a cumulative age calculation is 41.8 years.
 - 94.3% of the built square footage in the study area is 40 years of age or older.
- **Stable or decreasing population based upon the last two decennial census**
 - The study area has had a stable or decreasing population over the last two decennial census.

The other criteria for Blight were not present in the area, these included:

- Tax or special assessment delinquency exceeding fair value of the land.
- Defective or unusual condition of title,
- Unemployment in the designated area is at least 120% of the state or national average.
- The per capita income of the area is lower than the average per capita income of the city or village in which the area is designated.

These issues were either not present or were limited enough as to have little impact on the overall condition of the study area.

Substandard Conditions

Age of Structure

Age of structures can be a contributing factor to the blighted and substandard conditions in an area. Statutes allow for a predominance of structures 40 years of age or older to be a contributing factor regardless of their condition. The following paragraphs document the structural age of the structures within the Study Area. Note the age of structure was determined from the Appraisal data within the Hall County Assessor's website data.

TABLE 2: AVERAGE STRUCTURAL AGE, BY METHOD - 2018

Number	Year Built	Age	Cumulative Age	Running Total
1	1960	62	62	62
1	1970	52	52	114
15	1974	48	720	834
4	1975	47	188	1,022
1	1976	46	46	1,068
2	1978	44	88	1,156
1	1979	43	43	1,199
1	1980	42	42	1,241
2	1981	41	82	1,323
1	1989	33	33	1,356
3	1993	29	87	1,443
1	1995	27	27	1,470
2	1996	26	52	1,522
1	1998	24	24	1,546
1	2007	15	15	1,561
1	2021	1	1	1,562
35			Average	41.8

Source: Hall County Assessor's and Marvin Planning Consultants 2022

Another method to analyze this area is using square footage. State statute discusses commercial units; in the commercial world, it is not about the building as much as it is about square footage. Therefore, this analysis is also examining the age of the built square footage. Based upon data from the Hall County Assessor's office, there is a total of 647,019 built square footage in the area. Of the 647,019 total square footage, 610,089 built square feet are 40 years or older, which is 94.3% of the total build out. Therefore, more than 50% of the square footage is 40 years of age or older.

The final means to examine the age of structures is the actual number of structures within the 40 years or more or less than 40 years categories. Overall, there are 35 structures within the study area, based upon the Hall County Assessor's data (Hall County Assessor divides the primary mall structure into 11 separate units, thus 35 total). After researching the structural age on the Hall County Assessor's and Treasurer's websites, the following breakdown was determined:

- 28 (80.0%) unit were determined to be 40 years of age or older
- 7 (20.0%) unit were determined to be less than 40 years of age

However, when examining the age based upon a cumulative approach, as in Table 2, the average age of the primary structures is equal to 41.8 years; thus, meeting the requirements of the statutes.

The age of the structures would be a direct contributing factor.

Substandard Summary

Nebraska State Statute requires that “...an area in which there is a predominance of buildings or improvements, whether nonresidential or residential in character, which, by reason of dilapidation, deterioration, **age** or obsolescence, inadequate provision for ventilation, light, air, sanitation, or open spaces, high density of population and overcrowding, or the existence of conditions which endanger life or property by fire and other causes, or any combination of such factors, is conducive to ill health, transmission of disease, infant mortality, juvenile delinquency, and crime, (which cannot be remedied through construction of prisons), and is detrimental to the public health, safety, morals, or welfare;”

This Study Area in Grand Island meets the definition of Substandard as defined in the Revised Nebraska State Statutes.

FINDINGS FOR GRAND ISLAND BLIGHT STUDY AREA #28

Blight Study Area #28 has several items contributing to the Blight and Substandard Conditions. These conditions include:

Blighted Conditions under Part A

- Substantial number of deteriorating structures
- Deterioration of site or other improvements
- Diversity of Ownership
- Improper Subdivision or Obsolete Platting
- Faulty Lot Layout
- Combination of factors which are impairing and/or arresting sound growth
- Defective/Inadequate street layouts
- Insanitary and Unsafe Conditions
- Dangerous conditions to life or property due to fire or other causes

Criteria under Part B of the Blight Definition

- The average age of the residential or commercial units in the area is at least forty years
- Stable or decreasing population based upon the last two decennial census

Substandard Conditions

- Average age of the structures in the area is at least forty years

Asbestos Study

LIMITED NESHAP ASBESTOS SAMPLING REPORT

**Conestoga Mall
3404 W 13th Street
Grand Island, Nebraska**

**Prepared for:
Woodsonia Acquisitions, LLC
20010 Manderson Street Ste: 2
Elkhorn NE 68022**

August 5, 2022

**P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM**

HEARTLAND TESTING & CONSULTING, LLC

LIMITED NESHAP ASBESTOS SAMPLING REPORT

Date of Report: August 5, 2022

Project Name: Limited NESHAP Asbestos Inspection

Site Characterization: Conestoga Mall
3408 W 13th Street
Grand Island, NE 68803

Inspection Date: July 11th, July 12th, July 14th, July 21 & July 27, 2022

Inspector Name/License #: Michael A. Smith
NE Asbestos Inspector/Management Planner #920

Outside Information: None

Inspection Limitations: Inspection of the following occupied spaces were not completed due to no access: **Units 3A, 4, 7A, 9, 23B, 33, 34, 38 & 40**

Inspection of sub-flooring in the occupied tenant spaces of the facility were limited due to current sales area floor coverings. Additional review of the occupied spaces sales are sub-floors should be completed when the spaces are available for destructive review. Below is a summary of the spaces with limited review: **8, 9, 10, 12, 13, 17, 19, 20, 23A, 24, 30, 31, 36, 37, 39A, 40A, 41, 42, 44, 49, 50, 52, 54, 58, 59, 60, 62, Best Buy and Dillard's.**

Summarized Findings:

The following is a summary of the asbestos-containing materials identified in the inspection areas of the structure:

- Sample SR-2 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-4 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample SR-8 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample C-2 – Drywall Joint Compound contains 0.5% chrysotile asbestos.
- Sample C-8 – Ceiling Texture contains 10% chrysotile asbestos.
- Sample C-11 – Ceiling Texture contains 10% chrysotile asbestos.
- Sample Y-4 - 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample Y-10 - 12"x12" Tile contains 3% chrysotile asbestos.
- Sample 8B-1 – Black Mastic contains 4% chrysotile asbestos.
- Sample 41-1 – 12"x12" Tile contains 3% chrysotile asbestos.
- Sample 41-1 – Black Mastic contains 5% chrysotile asbestos.
- Sample 48-1 – Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample 48-2 - Vinyl Sheet Flooring contains 20% chrysotile asbestos.
- Sample JC-4 – 12"x12" Black Mastic contains 5% chrysotile asbestos.
- Sample JC-8 – Black/Yellow Mastic contains 2% chrysotile asbestos.
- Sample JC-9 – Black Mastic contains 4% chrysotile asbestos.
- Sample JC-10 – Silver/Black HVAC Sealant contains 6% chrysotile asbestos.
- Sample D-1 – Black mastic contains 5% chrysotile asbestos.
- Sample SRR-2 – Gray/Black Roof Patch contains 3% chrysotile asbestos.
- Assumed – Transite Panels at skylight soffit areas.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Any building material that contains greater than 1% asbestos is considered regulated and should be removed by a State of Nebraska certified asbestos abatement contractor prior to renovation or demolition activities.

Any presumed or building material known to contain <1% asbestos must be removed prior to renovation work to meet OSHA occupational exposure requirements.

Sample C-2: Wall Board System Joint Compound

The definition of asbestos-containing material (ACM) presented at 29 CFR 1910.1001(b), 29 CFR 1915(b), and 29 CFR 1926.1101(b); OSHA regards each of the items used to construct wall shells from wallboard panels as separate materials. Each of these materials that may contain asbestos must be analyzed separately for their asbestos content. OSHA does not regard wallboard/gypsum wallboard and joint compound as a surfacing material. If a wall shell is constructed of ACM joint compound and wallboard panels that are not ACM, then removal of the wall shell is considered OSHA Class II asbestos work.

For a full listing of materials tested please see table 1. Laboratory analytical results are presented in Appendix D. Asbestos sample photographs are presented in Appendix E. Facility diagram is presented in Appendix F.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Table 1: Sample Analysis Results

Material	Location	Quantity *	Asbestos %	Friable	Sample #
12"x12" Gray/Tan Mottled VFT w/ Yellow Mastic	Sears	-	ND	No	SR-1
VFT & Black Mastic (Under SR-1)	Sears	60,000 sf.	Mastic – 5% Chrysotile	No	SR-2
12"x12" Gray Mottled VFT w/ Yellow Mastic	Sears	-	ND	No	SR-3
VFT (Under SR-3) & Black Mastics	Sears	SR-2	Mastic – 5% Chrysotile	No	SR-4
12"x12" White/Black/Gray VFT w/ Yellow Mastic	Sears	-	ND	No	SR-5
12"x12" White w/ Black Streaked VFT w/ Yellow Mastic	Sears	-	ND	No	SR-6
Drywall	Sears	-	ND	No	SR-7
12"x12" Tan Mottled VFT & Black Mastic	Sears	SR-2	Mastic – 5% Chrysotile	No	SR-8
Drywall & Joint Compound (Composite)	Sears	-	ND	No	SR-9
12"x12" White w/ Black Specks VFT w/ Yellow Mastic	Sears	-	ND	No	SR-10
12"x12" Gray w/ Black Specks VFT w/ Yellow Mastic	Sears	-	ND	No	SR-11
2'x4' Ceiling Tile w/ Large/Small Dents	Corridors	-	ND	No	C-1
Drywall & Joint Compound	Original Structure	Walls & Ceilings	Joint Compound – 0.5%	No	C-2
Ceiling Texture	Corridor	-	ND	No	C-3
2'x4' Ceiling Tile w/ Pinholes & Large/Small Dents	Corridor	-	ND	No	C-4
Ceiling Texture	Corridor	-	ND	No	C-5
2'x4' Ceiling Tile w Fissures & Pinholes	Corridors	-	ND	No	C-6
Drywall & Joint Compound	Corridor	-	ND	No	C-7
Ceiling Texture	Original Corridor	13,000 sf.	10% Chrysotile	No	C-8
Ceiling Texture	Corridor	-	ND	No	C-9
2'x4' Ceiling Tile w/ Pinholes and Dents	Corridor	-	ND	No	C-10
Ceiling Texture	Original Corridor	C-8	10% Chrysotile	No	C-11
Wood Flooring w/ Black Mastic	Unit 5	-	ND	No	C-12
12"x12" Gray Mottled w/ Black Streaked VFT	Unit 5	-	ND	No	5-1
Black Baseboard	Unit 5	-	ND	No	5-2
Mudded Fitting	Unit 5	-	ND	No	5-3
12"x12" Tan Mottled VFT w/ Yellow Mastic	Younkers	-	ND	No	Y-1
12"x12" Gray VFT	Younkers	-	ND	No	Y-2
12"x12" White w/ Blue/Gray Streaked VFT & Yellow Mastic	Younkers	-	ND	No	Y-3
12"x12" Black VFT w/ Black Mastic	Younkers	10 sf.	Mastic – 5% Chrysotile	No	Y-4
12"x12" White w/ Brown Streaked VFT	Younkers	-	ND	No	Y-5
12"x12" VFT with ½" Square Pattern	Younkers	-	ND	No	Y-6
Drywall & Joint Compound	Younkers	-	ND	No	Y-7
Brown Baseboard w/ Brown Adhesive	Younkers	-	ND	No	Y-8
Mudded Pipe Hanger	Younkers	-	ND	No	Y-9
12"x12" White w/ Brown Streaked VFT & Black Mastic	Younkers	5,000 sf.	Tile – 3% Chrysotile	No	Y-10
12"x12" Blue/Green VFT	Younkers	-	ND	No	Y-11
12"x12" Off-White w/ Blue Streaked VFT	Younkers	-	ND	No	Y-12
Ceiling Texture (E & S Vestibules)	Younkers	C-8	10% Chrysotile	No	C-8
12"x12" Tan Mottled VFT & Yellow Mastic	Unit 8A	-	ND	No	8A-1
Tan Carpet Mastic	Unit 8A	-	ND	No	8A-2
ND-Non-Detect SF.-Square Foot LF.-Lineal Feet CT-Ceiling Tile VFT-Vinyl Floor Tile VSF-Vinyl Sheet Flooring					

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Material	Location	Quantity *	Asbestos %	Friable	Sample #
VSF w/ Mastic (Bathroom)	Unit 8B	80 sf.	Mastic - 4% Chrysotile	No	8B-1
12"x12" VFT w/ Yellow Mastic	Unit 8B	-	ND	No	8B-2
Gray Pebble Pattern VSF	Unit 11	-	ND	No	11-1
12"x12" White w/ Gray Streaked VFT	Unit 11	-	ND	No	11-2
Black Mastic	Unit 17	-	ND	No	17-1
12"x12" Tan Mottled VFT w/ Yellow Mastic	Unit 20-1	-	ND	No	20-1
12"x12" White w/ Brown Mottled VFT	Unit 23A-1	-	ND	No	23A-1
Black Mastic	Unit 24	-	ND	No	24-1
12"x12" White w/ Gray Mottled VFT	Unit 31	-	ND	No	31-1
Black Mastic	Unit 39	-	ND	No	39-1
VSF	Unit 40A	-	ND	No	40A-1
12"x12" Tan w/ Brown Pitted VFT & Black Mastic	Unit 41	300 sf.	Tile - 3% Chrysotile Mastic - 5% Chrysotile	No	41-1
12"x12" VFT and Mastic	Unit 42	-	ND	No	42-1
12"x12" Black VFT	Unit 43	-	ND	No	43-1
Tan VSF	Unit 48	150 sf.	20% Chrysotile	No	48-1
Tan Designed VSF	Unit 48	200 sf.	20% Chrysotile	No	48-2
Drywall & Joint Compound	Unit 48	-	ND	No	48-3
Wall Texture	Unit 48	-	ND	No	48-4
Mudded Fitting	Unit 48	-	ND	No	48-5
12"x12" VFT	Unit 49	-	ND	No	49-1
VSF	Unit 51	-	ND	No	51-1
12"x12" White w/ Black Streaked VFT	Unit 52	-	ND	No	52-1
12"x12" VFT	Unit 58	-	ND	No	58-1
12"x12" White w/ Black Streaked VFT & Yellow/Tan Mastic	Maint. Room	-	ND	NO	Maint-1
12"x12" Tan w/ Brown Streaked VFT & Black Mastic	JC Penny	-	ND	No	JC-1
12"x12" Brown VFT w/ Brown Mastic	JC Penny	-	ND	No	JC-2
12"x12" Black w/ White Streaked VFT	JC Penny	-	ND	No	JC-3
12"x12" Tan Marbled VFT & Black Mastic	JC Penny	30,000 sf.	Mastic - 5% Chrysotile	No	JC-4
12"x12" Beige Mottled VFT & Yellow Mastic	JC Penny	-	ND	No	JC-5
12"x12" Off-White/Tan Mottled VFT & Yellow Mastic	JC Penny	-	ND	No	JC-6
Ceiling Tile w/ Pinholes and Holes	JC Penny	-	ND	No	JC-7
Black/Yellow Mastic	JC Penny	JC-4	2% Chrysotile	No	JC-8
12"x12" White w/ Black Streaked VFT & Black Mastic (Sales Floor)	JC Penny	JC-4	Mastic - 4% Chrysotile	No	JC-9
Silver/Black HVAC Duct Sealant (JC Penny Roof)	JC Penny	80 sf.	6% Chrysotile	No	JC-10
12"x12" Cream w/ Brown Streaked VFT Black Mastic	Unit 16	-	ND	No	16-1
12"x12" Tan/Olive/Blue Mottled VFT	Unit 22	-	ND	No	22-1
12"x12" VFT (Under Carpet) w/ Yellow Carpet and Black Mastics	Paint Room	-	ND	No	PR-1
12"x12" Cream w/ Brown Streaked VFT & Black Mastic	Unit 57	-	ND	No	57-1
Tan 4" Square Design VSF	Unit 64	-	ND	No	64-1
12"x12" White w/ Black Streaked VFT & Yellow Mastic	Security Office	-	ND	No	SO-1
2'x2" Ceiling Tile w/ Deep Design	Civic Room	-	ND	No	CR-1
ND-Non-Detect SF-Square Foot LF-Lineal Feet CT-Ceiling Tile VFT-Vinyl Floor Tile VSF-Vinyl Sheet Flooring					

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Material	Location	Quantity *	Asbestos %	Friable	Sample #
Black Roof Flashing Tar	Sears Roof	-	ND	No	SRR-1
Gray/Black Patch Sealant	Sears Roof	1 sf.	3% Chrysotile	No	SRR-2
Black Roof Flashing Tar	Sears Roof	-	ND	No	SRR-3
Black Roof Tar	JCP Roof	-	ND	No	JCR-1
Black Speckled Asphalt Roll & Black Tar	JCP Roof	-	ND	No	JCR-2
Black Roof Tar	JCP Roof	-	ND	No	JCR-3
Black Speckled Asphalt Roll & Black Tar	JCP Roof	-	ND	No	JCR-4
VSF w/ Adhesive	Unit 8B	-	ND	No	8B-1
12"x12" VFT w/ Yellow Mastic	Unit 8B	-	ND	No	8B-2
Black Mastic	Unit 17	-	ND	No	17-1
12"x12" Tan Mottled VFT w/ Yellow Mastic	Unit 20	-	ND	No	20-1
12"x12" White w/ Brown Mottled VFT	Unit 23	-	ND	No	23A-1
Black Mastic	Unit 24	-	ND	No	24-1
12"x12" White w/ Gray Mottled VFT	Unit 31	-	ND	No	31-1
Black Mastic	Unit 39	-	ND	No	39-1
VSF	Unit 40A	-	ND	No	40A-1
12"x12" Tan w/ Brown Pitted VFT and Black Mastic	Unit 41	-	ND	No	41-1
12"x12" VFT and Yellow Mastic	Unit 42	-	ND	No	42-1
12"x12" Black VFT	Unit 43	-	ND	No	43-1
Mudded Fitting (Roof Drain)	Unit 48	-	ND	No	48-5
12"x12" VFT	Unit 49	-	ND	No	49-1
VSF	Unit 51	-	ND	No	51-1
12"x12" White w/ Black Streaked VFT	Unit 52	-	ND	No	52-1
12"x12" VFT	Unit 58	-	ND	No	58-1
Drywall & Joint Compound	Best Buy		ND	No	BB-1
Tan Vinyl Plank Flooring	Best Buy		ND	No	BB-2
12"x12" Blue/Gray Mottled VFT & Black Mastic	Dillard's	120,000 sf.	Mastic – 5% Chrysotile	No	D-1
Drywall	Dillard's		ND	No	D-2
12"x12" Tan w/ Blue Mottled VFT	Dillard's		ND	No	D-3
Mudded Fitting	Dillard's		ND	No	D-4
Transite Soffit Panels	Sky Light Areas	3,000 sf.	Assumed	No	----
ND-Non-Detect SF.-Square Foot LF.-Lineal Feet CT-Ceiling Tile VFT-Vinyl Floor Tile VSF-Vinyl Sheet Flooring					

*The quantities listed above are based upon the inspector's field measurements and are provided as estimates only.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Scope of Services

A visual inspection and sampling survey was conducted in general accordance with EPA/NESHAP guidelines to determine the presence of suspect asbestos-containing building materials (ACBM) in demolition and renovation projects.

Survey Methodology

This asbestos survey was performed by a State of Nebraska licensed asbestos inspector. An initial building walk through was conducted to determine the presence of suspect materials, homogeneous materials, and functional spaces throughout the facility. Following the walk through, the inspector collects samples of selected materials identified as suspect ACBM. Sampling is limited to those materials which do not involve destruction of building elements, physical barriers, or the structural integrity of the item being tested. Confined spaces and areas with structural deficiencies are also not inspected unless noted. EPA guidelines were used to determine the sampling protocol. Sampling locations were chosen to be representative of the homogeneous sampling area. While an effort was made to collect samples randomly, samples were taken preferentially from areas which were the least visible to minimize disturbance of the material.

Laboratory Methodology

Bulk samples obtained from the facility were analyzed at an accredited laboratory listed on the National Voluntary Laboratory Accreditation Program (NVLAP) using Polarized Light Microscopy (PLM) or point count methodology (PC) as needed. Laboratory certifications and statements of qualifications can be provided as needed.

Warranty

HTC and its inspectors are trained and licensed to perform the services provided. All care is taken to provide a product of the highest quality in line with professional standards. All care is taken to examine the entirety of the facility or area requested in so far as it is safe to do so. The value of the warranty or any claims cannot exceed the value paid for this report or survey.

Survey and Analysis Results

For a detailed report on laboratory findings please refer to Appendix D. Quantities of materials sampled are estimated from field measurements. Owner, contractor, or other operators should field verify all quantities to ensure accuracy.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

Appendix A – Licensing:

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM



Pete Ricketts, Governor

Public Health Licensure Unit Certification of Licensure

This certificate serves as primary source verification of licensure in the State of Nebraska as of the close of the business day before 6/24/2021.

Name: Michael Aaron Smith
Type: Asbestos Management Planner
Number: 920
Status: Active
Issued: 01/29/2015
Expiration: 02/28/2023
Education: None on record at this time

Disciplinary/Non-Disciplinary Information:

No disciplinary/non-disciplinary actions taken against this license.

If you have questions about this information, please contact the Licensure Unit at (402) 471-2115 or DHHS.LicensureUnit@nebraska.gov.

Helping People Live Better Lives



Appendix B – Regulatory Overview:

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

There are several government agencies with regulations pertaining to asbestos, renovation, and demolition projects in Nebraska. The following items are summaries of their involvement.

Environmental Protection Agency

Asbestos Hazard Emergency Response Act (AHERA) – This act contains many regulations pertaining exclusively to schools and can be found in 40 Code of Federal Regulation (CFR), Part 763.

National Emissions Standards for Hazardous Air Pollutants (NESHAP) – NESHAP regulations govern most of the asbestos related renovation and demolition projects. The full text can be found in 40 CFR. Part 61.

- Requires an asbestos inspection prior to renovation and demolition projects.
- Requires removal of materials prior to being disturbed by renovation or demolition activities.
- Requires ten government working day notification prior to any renovation, demolition, or asbestos removal activities on projects greater than 160 square feet or 260 lineal feet. All demolition projects must be notified regardless of if asbestos is present.
- Regulates the training requirements for asbestos professionals.
- Regulates the identification, removal, transportation, and disposal of asbestos containing materials.

Nebraska Department of Health & Human Services Asbestos Control Program

This state agency is delegated certain responsibilities created by the EPA regulations. For more information visit the programs website located at <https://dhhs.ne.gov/Pages/Asbestos.aspx>.

- Requires an asbestos inspection be performed by a licensed inspector prior to any renovation or demolition project. From the Program website:

“Before you begin demolition or renovation of a project by anyone other than a homeowner (in that person’s residential property of 4 units or less), each residential or commercial property owner must have a thorough inspection for asbestos-containing materials. This inspection must be performed by a Nebraska-certified asbestos inspector.”

- Requires a ten-day (14 calendar day) notification on projects greater than 160 square feet or 260 lineal feet.
- Requires state licensed personnel do all asbestos work except that exempted by the residential exemption found in glossary.
- Regulates work practices for all asbestos work.
- Enforces State regulations and some EPA regulations.

Nebraska Department of Environment and Energy (NDEE)

NDEQ regulations require removal of asbestos prior to demolition or renovation. NDEE also regulates the disposal of asbestos wastes and construction and demolition (C & D) materials.

- Requires use of personnel licensed in accordance with NDOH.
- Requires inspection and removal of ACM in demolition and renovations projects.
- Requires the same ten-day notification as above.
- Requires all asbestos waste be disposed of in a licensed landfill permitted to accept asbestos.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

- Requires all C&D material be disposed of or recycled in a permitted facility.
- Requires an inspection and removal of any ACM prior to a fire training exercise. Also requires disposal of ashes from said burn in a licensed landfill.

Occupational Safety and Health Administration (OSHA)

OSHA regulates asbestos as it pertains to the safety and health of all workers on site. Further information can be found in 29 cfr. 1926.1101.

- Requires owners of facilities to perform a survey of asbestos containing materials and institute an operations and maintenance plan to keep materials in good condition.
- Regulates work practices for removal and repair of ACM as it pertains to employee safety.
- Requires air monitoring be performed in certain situations to protect safety of asbestos workers as well as any other workers that may be in the area or structure.
- Requires medical monitoring, respiratory protection, and education of employees working with asbestos.
- OSHA may regulate materials whose asbestos content does not meet the EPA definition of an asbestos containing material.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

Appendix C - Glossary of Terms:

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

Approved Asbestos Waste Disposal Site - means a solid waste disposal area that is operated under a permit issued by the Nebraska Department of Environmental Quality and is authorized to receive asbestos containing solid wastes. See Appendix E.

Asbestos – means asbestiform varieties of chrysotile, crocidolite, amosite, anthophyllite, tremolite and actinolite.

Asbestos Containing Materials or ACM – means any material or product, which contains more than 1% asbestos.

Asbestos Project – means an asbestos encapsulation project, an asbestos removal project, an asbestos enclosure project, an asbestos related demolition project or an asbestos related dismantling project, but shall not include any activities which affect three (3) square feet or less or three (3) linear feet or less of ACM on or in a structure or equipment or any appurtenances thereto, or (b) any activities physically performed by a homeowner, a member of the home owner's family or an unpaid volunteer on or in the home owner's residential property of four units or less.

Bulk Sample – a solid quantity of a building material suspected of containing asbestos and that will be analyzed for the presence of asbestos.

Demolition – means the wrecking, razing, or removal of any structure or load-supporting structural item of any structure, including any related material handling operations, and includes the intentional burning of any structure.

Friable Asbestos – means asbestos in a form which can be crumbled, pulverized, or reduced to powder by hand pressure.

Caution: Non-friable asbestos which becomes friable is classified as friable asbestos.

Inspector – means an individual who is certified by the Department to identify and assess the condition of ACM. Inspectors shall perform their duties in accordance with the techniques, knowledge, training and responsibilities outlined in 008.04A8.

Management Planner – means an individual who is certified by the Department to assess the hazard of materials containing asbestos, to determine the appropriate response actions and to write management plans.

Non-friable ACM – any material containing more than one percent asbestos (as determined by Polarized Light Microscopy), that when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure, Nonfriable asbestos is further divided into categories I and II. Category I includes packings, gaskets, resilient floor covering, and asphalt roofing. Category II includes any material not in Category I.

Project Designer – means an individual who is certified by the Department to formulate plans and write specifications for conducting asbestos projects.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

RACM – Regulated Asbestos-Containing Material (ACM) is:

- Friable asbestos;
- Category I non-friable ACM that has become friable due to destructive handling;
- Category I non-friable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading; or
- Category II non-friable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material during demolition or renovation operations regulated by the Asbestos National Emission Standard for Hazardous Air Pollutants (NESHAP).

Renovation – means the altering of a structure, one or more structural items, or one or more equipment items in any way, including any asbestos project performed on a structure, structural item, or equipment item.

Structure or Structural Item – means roofs, walls, ceilings, floors, structural supports, pipes, ducts, fittings and fixtures that have been installed as an integral part of any structure.

Thermal System Insulation (TSI) – ACM applied to pipes, fittings, boilers, breeching, tanks, ducts or other structural components to prevent heat loss or gain.

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

Appendix D – Laboratory Analytical Results

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116

Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138748
Project #: 2973888
Date Received: 13-Jul-2022
Date Analyzed: 14-Jul-2022
Date Reported: 15-Jul-2022

EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents		Non-Asbestos Constituents	
SR-1	LAYER 1 Floor Tile, Beige, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%
SR-2	LAYER 1 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Floor Tile, Beige, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 3 Mastic, Black, Homogeneous	Chrysotile	5%	Non-Fibrous Material	95%
SR-3	LAYER 1 Floor Tile, Off White, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%
SR-4	LAYER 1 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Floor Tile, White, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 3 Mastic, Black, Homogeneous	Chrysotile	5%	Non-Fibrous Material	95%
SR-5	LAYER 1 Floor Tile, Gray, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%

Anh Phung

Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 200525-0

TDSHS License: 30-0273

Page 1 of 5

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116

Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138748
Project #: 2973888
Date Received: 13-Jul-2022
Date Analyzed: 14-Jul-2022
Date Reported: 15-Jul-2022

EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents	
SR-6	LAYER 1 Floor Tile, Lt. Gray, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
SR-7	Wallboard, Brown/ White, Homogeneous	None Detected	Cellulose Fiber Fibrous Glass Non-Fibrous Material	10% <1% 90%
SR-8	LAYER 1 Mastic, Gray/ Clear, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Floor Tile, Beige, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 3 Mastic, Black, Homogeneous	Chrysotile 5%	Non-Fibrous Material	95%
SR-9	LAYER 1 Joint Compound, White, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Wallboard, Brown/ White, Homogeneous	None Detected	Cellulose Fiber Fibrous Glass Non-Fibrous Material	10% <1% 90%
SR-10	LAYER 1 Mastic, Gray/ Clear, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Floor Tile, Off White, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 3 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%

Anh Phung

Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 200525-0

TDSHS License: 30-0273

Page 2 of 5

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116

Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138748
Project #: 2973888
Date Received: 13-Jul-2022
Date Analyzed: 14-Jul-2022
Date Reported: 15-Jul-2022

EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents	
SR-11	LAYER 1 Floor Tile, Gray, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
C-1	Ceiling Tile, White/ Gray, Homogeneous	None Detected	Cellulose Fiber Mineral Wool Non-Fibrous Material	60% 20% 20%
C-2	LAYER 1 Joint Compound, Beige, Homogeneous	Chrysotile 2%	Non-Fibrous Material	98%
	LAYER 2 Wallboard, Brown/ White, Homogeneous	None Detected	Cellulose Fiber Fibrous Glass Non-Fibrous Material	10% <1% 90%
C-3	Ceiling Texture, White, Homogeneous	None Detected	Non-Fibrous Material	100%
C-4	Ceiling Tile, White/ Gray, Homogeneous	None Detected	Cellulose Fiber Mineral Wool Non-Fibrous Material	60% 20% 20%
C-5	Ceiling Texture, White, Homogeneous	None Detected	Non-Fibrous Material	100%
C-6	Ceiling Tile, White/ Gray, Homogeneous	None Detected	Cellulose Fiber Mineral Wool Non-Fibrous Material	60% 20% 20%

Anh Phung

Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 200525-0

TDSHS License: 30-0273

Page 3 of 5

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116

Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138748
Project #: 2973888
Date Received: 13-Jul-2022
Date Analyzed: 14-Jul-2022
Date Reported: 15-Jul-2022

EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents		Non-Asbestos Constituents	
C-7	LAYER 1 Joint Compound, White, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Wallboard, Brown/ White, Homogeneous	None Detected		Cellulose Fiber Fibrous Glass Non-Fibrous Material	10% <1% 90%
C-8	Ceiling Texture, White, Homogeneous	Chrysotile	10%	Non-Fibrous Material	90%
C-9	Ceiling Texture, White, Homogeneous	None Detected		Non-Fibrous Material	100%
C-10	Ceiling Tile, White/ Gray, Homogeneous	None Detected		Cellulose Fiber	70%
				Mineral Wool	10%
				Non-Fibrous Material	20%
C-11	Ceiling Texture, White, Homogeneous	Chrysotile	10%	Non-Fibrous Material	90%
C-12	LAYER 1 Wood Flooring, Brown, Homogeneous	None Detected		Cellulose Fiber	100%
	LAYER 2 Mastic, Brown, Homogeneous No Black Mastic Present	None Detected		Cellulose Fiber Non-Fibrous Material	2% 98%
32-1	LAYER 1 Floor Tile, Tan, Homogeneous	None Detected		Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected		Non-Fibrous Material	100%

Anh Phung

Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 200525-0

TDSHS License: 30-0273

Page 4 of 5

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116


Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138748
Project #: 2973888
Date Received: 13-Jul-2022
Date Analyzed: 14-Jul-2022
Date Reported: 15-Jul-2022

EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents	
8A-1	LAYER 1 Floor Tile, Tan, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%

Anh Phung Analyst



Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)
EPA 600/M4-82-020; 600/R-93/116 - Point Count Method


Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JH22138951
Project #: 2973888
Date Received: 20-Jul-2022
Date Analyzed: 20-Jul-2022
Date Reported: 22-Jul-2022

PC-JH22138748-EMLab ID 2973888

Sample ID #	Sample Description	Asbestos Constituents		Non-Asbestos Constituents	
C-2 LAYER 1	Joint Compound, Beige, Homogeneous Original PLM Result: Chrysotile 2%	Chrysotile	0.50%	Non-Fibrous Material	99.50%
400 pt. POINT COUNT					

Taylor Smylie Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 200525-0

TDSHS License: 30-0273

Page 1 of 1

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

Total Samples Submitted:	29
Total Samples Analyzed:	29
Total Samples with Layer Asbestos Content > 1%:	4

Lab ID-Version†: 14304823-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

Lab ID-Version†: 14304824-1

Sample Layers	Asbestos Content
Black Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

Lab ID-Version†: 14304825-1

Sample Layers	Asbestos Content
Gray Semi-Fibrous Material	ND
Composite Non-Asbestos Content:	15% Glass Fibers 5% Cellulose
Sample Composite Homogeneity:	Good

Lab ID-Version†: 14304826-1

Sample Layers	Asbestos Content
Tan Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

EMLab ID: 2974469, Page 2 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: Y-2, 12"x12" Gray VFT

Lab ID-Version‡: 14304827-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 3 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: Y-3, 12"x12"White w/ Blue/Gray Streaked VFT w/ Yellow Mastic Lab ID-Version‡: 14304828-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: Y-4, 12"x12" Black VFT w/ Black Mastic Lab ID-Version‡: 14304829-1

Sample Layers	Asbestos Content
Black Floor Tile	ND
Black Mastic	5% Chrysotile
Sample Composite Homogeneity: Moderate	

Location: Y-5, 12"x12" White w/ Brown Streaked VFT Lab ID-Version‡: 14304830-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: Y-6, 12"x12" VFT w/ 1/2" Square Pattern Lab ID-Version‡: 14304831-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Sample Composite Homogeneity: Good	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 4 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: Y-7, Drywall & Joint Compound (COMPOSITE SAMPLE) Lab ID-Version‡: 14304832-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: Y-8, Brown Baseboard w/ Brown Adhesive Lab ID-Version‡: 14304833-1

Sample Layers	Asbestos Content
Brown Baseboard	ND
Brown Mastic	ND
Sample Composite Homogeneity:	Moderate

Location: Y-9, Mudded Pipe Hager Fitting Lab ID-Version‡: 14304834-1

Sample Layers	Asbestos Content
Gray Semi-Fibrous Material	ND
Composite Non-Asbestos Content:	15% Glass Fibers 5% Cellulose
Sample Composite Homogeneity:	Good

Location: 11-1, Gray Pebble Pattern VSF Lab ID-Version‡: 14304835-1

Sample Layers	Asbestos Content
Gray Sheet Flooring with Fibrous Backing	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 5 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: 11-2, 12"x12" White w/ Gray Streaked VFT w/ Yellow Mastic Lab ID-Version‡: 14304836-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

Location: 48-1, Tan VSF Lab ID-Version‡: 14304837-1

Sample Layers	Asbestos Content
Tan Sheet Flooring with Fibrous Backing	20% Chrysotile
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: 48-2, Tan Designed VSF Lab ID-Version‡: 14304838-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Tan Sheet Flooring with Fibrous Backing	20% Chrysotile
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 48-3, Drywall & Joint Compound Lab ID-Version‡: 14304839-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 6 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: 48-4, Wall Texture

Lab ID-Version‡: 14304840-1

Sample Layers	Asbestos Content
White Texture	ND
Sample Composite Homogeneity: Good	

Location: Maint-1, 12"x12" White w/ Black Streaked VFT w/ Tan-Yellow Mastic

Lab ID-Version‡: 14304841-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: JC-1, 12"x12" Tan w/ Brown Streaked VFT w/ Black Mastic

Lab ID-Version‡: 14304842-1

Sample Layers	Asbestos Content
Tan Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: JC-2, 12"x12" Brown VFT w/ Brown Mastic

Lab ID-Version‡: 14304843-1

Sample Layers	Asbestos Content
Brown Floor Tile	ND
Brown Mastic	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 7 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: JC-3, 12"x12" Black w/ White Streaked VFT Lab ID-Version‡: 14304844-1

Sample Layers	Asbestos Content
Black Floor Tile	ND
Sample Composite Homogeneity: Good	

Location: JC-4, 12"x12" Tan Mottled VFT w/ Yellow Mastic Lab ID-Version‡: 14304845-1

Sample Layers	Asbestos Content
Tan Floor Tile	ND
Black Mastic	5% Chrysotile
Sample Composite Homogeneity: Moderate	

Location: JC-5, 12"x12" Beige Mottled VFT w/ Yellow Mastic Lab ID-Version‡: 14304846-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Sample Composite Homogeneity: Good	

Location: JC-6, Off-White w/ Tan Mottled VFT w/ Yellow Mastic Lab ID-Version‡: 14304847-1

Sample Layers	Asbestos Content
Off-White Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 8 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-11-2022
Date of Receipt: 07-13-2022
Date of Report: 07-18-2022

ASBESTOS PLM REPORT

Location: JC-7, 2x4 CT w/ Pineholes and Holes

Lab ID-Version‡: 14304848-1

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose 40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 16-1, 12"x12" Cream w/ Brown Streaked VFT w/ Black Mastic

Lab ID-Version‡: 14304849-1

Sample Layers	Asbestos Content
Cream Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity:	Moderate

Location: 22-1, Tan/Olive/Blue Mottled VFT

Lab ID-Version‡: 14304850-1

Sample Layers	Asbestos Content
Tan Floor Tile	ND
Sample Composite Homogeneity:	Good

Location: PR-1, 12"x12" VFT (Under Carpet in Restroom)

Lab ID-Version‡: 14304851-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Cream Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2974469, Page 9 of 9

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-12-2022
Date of Receipt: 07-14-2022
Date of Report: 07-19-2022

ASBESTOS PLM REPORT

Total Samples Submitted:	12
Total Samples Analyzed:	12
Total Samples with Layer Asbestos Content > 1%:	1

Location: CR-1, 2x2 CT w/ Deep Design

Lab ID-Version‡: 14309731-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	60% Glass Fibers 20% Cellulose
Sample Composite Homogeneity:	Good

Location: SO-1, 12x12 White w/ Black Streaked VFT and Yellow Mastic

Lab ID-Version‡: 14309732-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

Location: 8A-2, Yellow Carpet Mastic

Lab ID-Version‡: 14309733-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Sample Composite Homogeneity:	Good

Location: 57-1, 12x12 Cream w/ Beige Streaked VFT w/ Black Mastic

Lab ID-Version‡: 14309734-1

Sample Layers	Asbestos Content
Cream Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2975278, Page 2 of 4

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-12-2022
Date of Receipt: 07-14-2022
Date of Report: 07-19-2022

ASBESTOS PLM REPORT

Location: 64-1, Tan Square Design VSF

Lab ID-Version‡: 14309735-1

Sample Layers	Asbestos Content
Tan Sheet Flooring with Fibrous Backing	ND
Composite Non-Asbestos Content:	20% Cellulose
Sample Composite Homogeneity:	Good

Location: SRR-1, Black Flashing Tar

Lab ID-Version‡: 14309736-1

Sample Layers	Asbestos Content
Black Roof Flashing	ND
Sample Composite Homogeneity:	Good

Location: SRR-2, Black Flashing Tar

Lab ID-Version‡: 14309737-1

Sample Layers	Asbestos Content
Gray/Black Roof Flashing	3% Chrysotile
Sample Composite Homogeneity:	Good

Location: SRR-3, Black Flashing Tar

Lab ID-Version‡: 14309738-1

Sample Layers	Asbestos Content
Black Roof Flashing	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2975278, Page 3 of 4

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-12-2022
Date of Receipt: 07-14-2022
Date of Report: 07-19-2022

ASBESTOS PLM REPORT

Location: JCR-1, Black Roof Tar

Lab ID-Version‡: 14309739-1

Sample Layers	Asbestos Content
Black Roofing Tar	ND
Sample Composite Homogeneity:	Good

Location: JCR-2, Black Asphalt Roll w/ Black Tar

Lab ID-Version‡: 14309740-1

Sample Layers	Asbestos Content
Black Roofing Material with Grey Pebbles	ND
Black Tar	ND
Sample Composite Homogeneity:	Moderate

Location: JCR-3, Black Roof Tar

Lab ID-Version‡: 14309741-1

Sample Layers	Asbestos Content
Black Roofing Tar	ND
Sample Composite Homogeneity:	Good

Location: JCR-4, Black Asphalt Roll w/ Black Tar

Lab ID-Version‡: 14309742-1

Sample Layers	Asbestos Content
Black Roofing Material with Grey Pebbles	ND
Black Tar	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2975278, Page 4 of 4

Eurofins J3 Resources, Inc.

3113 Red Bluff Road, Pasadena, TX 77503

Phone: (713) 290-0223 - Fax: (713) 290-0248

J3Resources.com



J3 Resources

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116


Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JP221037792
Project #: 2982869
Date Received: 26-Jul-2022
Date Analyzed: 27-Jul-2022
Date Reported: 27-Jul-2022

EMLab ID 2982869

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents	
8B-1	LAYER 1 Sheet Flooring, Beige, Homogeneous	None Detected	Fibrous Glass Non-Fibrous Material	4% 96%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 3 Float, Gray, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 4 Mastic, Black, Homogeneous	Chrysotile 4%	Non-Fibrous Material	96%
8B-2	LAYER 1 Floor Tile, White, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
17-1	Mastic, Black, Homogeneous	None Detected	Cellulose Fiber Non-Fibrous Material	5% 95%
20-1	LAYER 1 Floor Tile, Tan/ Mottled, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
23A-1	Floor Tile, White/Brown/ Mottled, Homogeneous	None Detected	Non-Fibrous Material	100%
24-1	Mastic, Black, Homogeneous	None Detected	Cellulose Fiber Non-Fibrous Material	5% 95%
31-1	Floor Tile, White/ Gray/ Mottled, Homogeneous	None Detected	Non-Fibrous Material	100%

Duane Salinas Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 600120-0 AIHA-LAP, LLC Lab ID: 157714 TDSHS License: 30-0457 Page 1 of 4

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116

Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JP221037792
Project #: 2982869
Date Received: 26-Jul-2022
Date Analyzed: 27-Jul-2022
Date Reported: 27-Jul-2022

EMLab ID 2982869

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents	
39-1	Mastic, Black, Homogeneous	None Detected	Non-Fibrous Material	100%
40A-1	LAYER 1 Sheet Flooring, White, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
41-1	LAYER 1 Floor Tile, Tan/Brown/Pitted, Homogeneous	Chrysotile 3%	Non-Fibrous Material	97%
	LAYER 2 Mastic, Black, Homogeneous	Chrysotile 5%	Non-Fibrous Material	95%
42-1	LAYER 1 Floor Tile, White/Gray Streaks, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%
43-1	Floor Tile, Black, Homogeneous	None Detected	Non-Fibrous Material	100%
48-5	Mud Insulation, Gray, Homogeneous	None Detected	Fibrous Glass	25%
			Non-Fibrous Material	75%
49-1	LAYER 1 Floor Tile, White, Homogeneous	None Detected	Non-Fibrous Material	100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material	100%

Duane Salinas Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 600120-0 AIHA-LAP, LLC Lab ID: 157714 TDSHS License: 30-0457 Page 2 of 4

Eurofins J3 Resources, Inc.

3113 Red Bluff Road, Pasadena, TX 77503

Phone: (713) 290-0223 - Fax: (713) 290-0248

J3Resources.com



J3 Resources

Bulk Asbestos Fiber Analysis by Polarized Light Microscopy (PLM)

Appx E Sub E 40 CFR 763 / EPA 600/R-93/116


Donnie Combs
Eurofins EMLab P&K - Houston
10900 Brittmoore Park Drive, Ste. G
Houston TX 77041

Order #: JP221037792
Project #: 2982869
Date Received: 26-Jul-2022
Date Analyzed: 27-Jul-2022
Date Reported: 27-Jul-2022

EMLab ID 2982869

Sample ID #	Sample Description	Asbestos Constituents	Non-Asbestos Constituents
51-1	Sheet Flooring, Beige, Homogeneous	None Detected	Cellulose Fiber 20% Fibrous Glass 2% Non-Fibrous Material 78%
52-1	LAYER 1 Floor Tile, White/Black Streaks, Homogeneous	None Detected	Non-Fibrous Material 100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material 100%
58-1	LAYER 1 Floor Tile, Tan, Homogeneous	None Detected	Non-Fibrous Material 100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material 100%
Y-10	LAYER 1 Floor Tile, White/Brown Streaks, Homogeneous	Chrysotile 3%	Non-Fibrous Material 97%
	LAYER 2 Mastic, Black, Homogeneous	None Detected	Cellulose Fiber 2% Non-Fibrous Material 98%
Y-11	LAYER 1 Floor Tile, Blue/ Green, Homogeneous	None Detected	Non-Fibrous Material 100%
	LAYER 2 Mastic, Yellow, Homogeneous	None Detected	Non-Fibrous Material 100%
Y-12	Floor Tile, White/Blue Streaks, Homogeneous	None Detected	Non-Fibrous Material 100%
JC-8	Mastic, Black/ Yellow, Homogeneous	Chrysotile 2%	Non-Fibrous Material 98%

Duane Salinas Analyst


Scott Ward, Ph.D. Lab Director

Results apply to the sample as received and relate only to the items tested. This report is for the exclusive use of the addressed client and shall not be reproduced except in full, without written approval by Eurofins J3 Resources, Inc. (EJ3). Samples are analyzed according to the methods listed above and are subject to the inherent limitations of PLM and interference of matrix components. Reporting limit for the above method is a function of the quantity of sample analyzed, matrix interference, sample preparation, fiber size, and distribution. Asbestos may be detected in concentrations of <1% by area if sufficient material is analyzed. All reported results have been determined by calibrated visual estimation (CVE) unless otherwise noted. According to the USEPA 1991 Clarification and the Texas Asbestos Health Protection Rule, a material containing asbestos of <10% by CVE (including <1% asbestos) can only be demonstrated as a non-asbestos containing building material (non-ACBM) if confirmed by point counting. EJ3 recommends TEM confirmation of soils, vermiculite and non-friable organically bound materials (NOB) reported as None Detected or < 1% Asbestos by PLM. All samples received in good condition unless otherwise noted. This report shall not be used to claim product approval, certification, or endorsement by NVLAP, NIST, or any agency of the federal government.

NVLAP Lab Code: 600120-0 AIHA-LAP, LLC Lab ID: 157714 TDSHS License: 30-0457 Page 3 of 4

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-27-2022
Date of Receipt: 07-28-2022
Date of Report: 08-02-2022

ASBESTOS PLM REPORT

Total Samples Submitted:	6
Total Samples Analyzed:	6
Total Samples with Layer Asbestos Content > 1%:	1

Location: BB-1, Drywall and Joint Compound

Lab ID-Version‡: 14372398-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound with Paint	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: BB-2, Tan Vinyl Plank Flooring

Lab ID-Version‡: 14372399-1

Sample Layers	Asbestos Content
Tan Sheet Flooring	ND
Sample Composite Homogeneity:	Good

Location: D-1, 12"x12" Tan w/ Lt. Blue/Gray Mottled VFT & Black Mastic

Lab ID-Version‡: 14372400-1

Sample Layers	Asbestos Content
Tan Floor Tile	ND
Black Mastic	5% Chrysotile
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2987259, Page 2 of 3

Client: Heartland Testing & Consulting
C/O: Mike Smith
Re: Conestoga Mall; NESHAP

Date of Sampling: 07-27-2022
Date of Receipt: 07-28-2022
Date of Report: 08-02-2022

ASBESTOS PLM REPORT

Location: D-2, Drywall

Lab ID-Version‡: 14372401-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: D-3, 12"x12" Beige/Tan Mottled VFT

Lab ID-Version‡: 14372402-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Sample Composite Homogeneity:	Good

Location: D-4, Mudded Fitting

Lab ID-Version‡: 14372403-1

Sample Layers	Asbestos Content
White Semi-Fibrous Material	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 2987259, Page 3 of 3

Appendix E – Asbestos Sample Photographs

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

	<p>Photo 1:</p> <p>View of Sample SR-1 & SR-2.</p>
	<p>Photo 2:</p> <p>View of Sample SR-3 & SR-4.</p>

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC



Photo 3:

**View of
Sample SR-8.**



Photo 4:

**View of sample
C-2.**

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC



Photo 5:

**View of
Sample C-8 &
C-11.**



Photo 6:

**View of
Sample Y-4 &
Y-10.**

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC



Photo 7:

**View of
Sample 41-1.**






Photo 8:

**View of
Sample 48-1.**

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

HEARTLAND TESTING & CONSULTING, LLC

	<p>Photo 9:</p> <p>View of Sample 48-2.</p>
	<p>Photo 10:</p> <p>View of Sample JC-4.</p>

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM



Photo 11:

**View of
Sample JC-10.**



Photo 12:

**View of
Sample SRR-2,
material
appears to be a
patch material.**

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM



Photo 13:

**View of
sample D-1.**



Photo 14:


**View of
Assumed
transite soffit.**


P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

Appendix F – Facility Diagrams

P.O. BOX 290 • ALDA • 6 8 8 10
PHONE: (3 0 8) 708-0604 • FAX: (3 0 8) 3 8 1 - 1 6 9 7
MIKE@ONEILLWR.COM

SAMPLE Locations





Resolution Number 2023-03

HALL COUNTY REGIONAL PLANNING COMMISSION

A RESOLUTION RECOMMENDING APPROVAL OF A BLIGHT AND SUBSTANDARD STUDY BY THE CITY OF GRAND ISLAND, NEBRASKA; AND APPROVAL OF RELATED ACTIONS

WHEREAS, the Grand Island City Council at its September 13, 2022 meeting, referred **the Blight and Substandard Study commissioned by Woodsonia Acquisitions LLC** to the Hall County Regional Planning Commission, (the “**Commission**”) for review and recommendation as to its conformity with the general plan for the development of the City of Grand Island, Hall County, Nebraska, pursuant to the Nebraska Community Development Law, Chapter 18, Article 21, Reissue Revised Statutes of Nebraska, as amended (the “**Act**”); and

WHEREAS, the Commission has reviewed said Blight and Substandard Study and confirmed the following findings:

- This property as presented in the study meets the requirements to be declared substandard,
- This property as presented in the study meets the requirements to be declared blighted,
- The factors are necessary to declare the property blighted and substandard are sufficiently distributed to impact development across the entire site,
- That development of this property to its full potential is in the best interest of the City of Grand Island and the entire region,
- That there are projects ready to develop at this site if they can meet the financial goals of the developers,

NOW, THEREFORE, BE IT RESOLVED BY THE HALL COUNTY REGIONAL PLANNING COMMISSION AS FOLLOWS:

Section 1. The Commission hereby recommends approval of the Blight and Substandard Study.

Section 2. All prior resolutions of the Commission in conflict with the terms and provisions of this resolution are hereby expressly repealed to the extent of such conflicts.

Section 3. This resolution shall be in full force and effect from and after its passage as provided by law.

DATED: October 5, 2023.

**HALL COUNTY REGIONAL PLANNING
COMMISSION**

ATTEST:

By: _____
Chair

By: _____
Secretary