



---

# **Le Sueur County, MN**

**Tuesday, April 18, 2017**

**Board Meeting**

## **Item 9**

**10:20 a.m. Nik Kadel, Ditch Inspector (10 minutes)**

***RE: Ditch Report***

**Staff Contact:**

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD6	16-057	2016-10-10	Montgomery	17	VLASAK FARMS		culvert needs to be installed	selly		10/10/2016	12/10/2016	\$ 8,398.56	spot cleaning was done, need meeting with selly.
CD6	16-028	2016-10-04	Montgomery	7	RYNDA,WILLIAM J	Jerry Selly	Culvert Replacements (2) on each end of the line, the work is done, this is for follow up repairs.	Selly		10/4/2016	12/1/2016	18610	Selly did cleaning and came back to do repairs on culvert. These are to different repairs tied to one project on CD6.
CD15	16-033	2016-10-18	Kilkenny	22	MCGILLEN,JOHN E & PAMELA K	MCGILLEN,JOHN E & PAMELA K		Barnette		12/23/2016			Barnettes will be removing beaver dams.
CD16	16-037	2016-11-01	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	2016-11-03	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	2016-11-03	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Waiting for dnr permits
CD21	16-007	2016-04-25	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD22	16-062	2016-12-30	Montgomery	10	SENECA FOODS CORP	Chris Reomhell	Needs to be checked out, wants cleaning done before or by spring. Needs to be checked with county.	Selly	N/A	2/1/2017		\$ -	The city of Montgomery is in charge of this ditch
CD23	16-024	2016-09-29	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch spection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	2016-11-14				Don Westerman	Don Westerman wants the outlet structure for marks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD31	16-055	2016-12-05			JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						needs inspection once snow melts.
CD36	17-001	2017-01-03	Elysian	3	SPRAGUE,JOHN & LISA	jack sprague	The control structure in which the ditch runs through needs to be checked out once the water is on a low point.						needs inspection once water drops to check structure.

Le Sueur County Ditch Report: 4/1/17    ■ =New    ■ =Closed    white=current    ■ = In Review

CD38	16-053	2016-11-30	Kilkenny	27	STANGLER FAMILY FARM LLC	STANGLER FAMILY FARM LLC	Remove 2 culverts that are restricting flow. Stangler also wants remove the crossing. He says he can get a contractor to do the work for cheaper.						This is at landowner cost. Need to keep in contact just to see what he does. The county will not pay for it.
CD40	16-061	2016-12-21	Montgomery	22	BAUER, LEROY O & BONNIE K	BAUER, LEROY O & BONNIE K	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Needs inspection once snow melts.
CD40	17-004	2017-01-12	Montgomery	26	KORBEL, DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	2016-09-21	Montgomery	28	KRAUTKREMER, DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD40	17-003	2017-01-04	Montgomery	28	WENKER, JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	7000				in progress
CD41	17-013	3/31/2017	Lexington	30	Beers	Jerry Cooney	Tile Holding back water. Needs to be replaced or fixed.	Selly		3/31/2017			In progress
CD41	16-059	2016-12-13	Sharon	25	TRAXLER, DOUGLAS R & BARBARA	TRAXLER, DOUGLAS R & BARBARA	tree removal and spot clean out. gravel at Hewitt crossing.	Selly			12/13/2016	\$5,180.00	
CD43	17-007	2017-02-03	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake						Waiting on dnr permit.
CD44	16-035	2016-10-20	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-045	2016-11-16	Lanesburgh	20	STELLA, MICHAEL J & SHIRLEY A		LO has requested that the ditch crossing be repaired.						
CD44	16-054	2016-11-30	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						
CD44	16-038	2016-11-01				Rusty Tiede	Collapsed culvert	Braith Excavating		11/1/2016	12/7/2016	1445	done
CD45	16-048	2016-11-21	Derrynane	33	BLASCHKO, DANIEL L	BLASCHKO, DANIEL L	sloughing 40 yards from road. NE side of 221						will have to be checked east of shae lake for repairs.
CD45	17-005	2017-01-27	Derrynane	27	WACKER, MARK W								needs inspection once ice and snow melts, looks to be backing up somewhere west.
CD45	16-036	2016-11-01	Derrynane	29	THEIS, BRADLEY M	Rusty Tiede		Zimmerman		11/15/2016	12/9/2016	9129.01	Worked with DNR to clean out damns and clean out to road. Done

														Came in about crossing eroding away, talked to havel about fixing it when he is working on the CD40 crossing.
CD46	16-060	2016-12-13	Montgomery	28	PICKA FAMILY FARM TRUST	PICKA FAMILY FARM TRUST	A crossing has been eroding away and needs repair.							
CD46	16-025	2016-09-29	Montgomery	28	KRAUTKREMER,GENE O & LINDA C		Culvert in Disrepair. Rotting out.	Havel						Talked to havel, he said he has not had time to replace culvert. Will get to it this spring.
CD47	16-034	2016-10-19	Cleveland	20	PONWITH,BRUCE	PONWITH,BRUCE	Site need a general cleaning in the upper reach of the ditch. Lower end needs a side inlet and several sloughs pulled out.	Zimmerman		10/19/2016	12/5/2016	\$12,400.00		
CD47	16-043	2016-11-14	Cleveland	19			Apply for DNR Public Water Permit to clean out into the cattails. All work north of HWY 99 will take place once permit is approved.							Permit came in now waiting for it to warm up to get someone to clean out the rest
CD48	16-032	2016-10-14	Montgomery	6	AUGST,NORMAN A & PATRICIA	Brian Rynda	Culvert for field crossing is rusted out and collapsing	Braith Excavating		10/14/2016	12/21/2016	\$5,270.90		
CD51	17-006	2017-02-02				Anthony Beers	Check to see if needs ditch cleaning							need inspection.
CD58	16-022	2016-09-27	Cleveland	28	LOEFFLER,LYNN L & DEBRA A	LOEFFLER,LYNN L & DEBRA A	Ditch bank sloughed and needs to be repaired.	Zimmerman		9/27/2016	1/17/2017	\$600.00		
CD58	16-047	2016-11-17	Cleveland	33		Lynn Krenik	Ditch is holding some water back, several locations have sloughs and vegetation in the ditch.	Zimmerman		11/17/2016	12/13/2016	\$4,960.00		
CD59	16-017	2016-09-23	Elysian	3	DOMONOSKE,DONALD & JUDY	Donald Domonoske		Zimmerman		10/3/2016	11/21/2016	\$ 6,240.00		Work has been finished and paid for. This was left in progress because more calls about different parts needing cleaning.
CD59	16-018	2016-09-23	Elysian	11	QUAST,MILO & VIVIAN	Donald Domonoske	Sloughs and build a diversion on the east end to the waterway on co. hwy 7.	Zimmerman		9/23/2016	12/7/2016	\$6,240.00		
CD61	16-013	2016-09-20	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017				Traxler is looking into the problem and will report back.
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.							needs inspection.
CD64	16-056	2016-12-09	Cordova	20	SCHMIDT,JOEL		tree removal and some clean up	Zimmerman		12/9/2016	12/13/2016	\$900.00		
CD68	16-021	2016-09-23	Cordova	27	NOVOTNY,MARVIN G	Roger Hoenstadt		Zimmerman		9/23/2016	1/19/2017	\$3,059.80		

Le Sueur County Ditch Report: 4/1/17    ■ =New    ■ =Closed    white=current    ■ = In Review

CD70	16-026	2016-09-29	Tyrone	16	O'BRIEN,MARY GRACE	Dale Kessler	Sediment and vegetation has built up and ditch needs cleaning.	Selly	22260	9/29/2016	12/12/2016	\$ 45,177.30	Work has been finished and he has been paid for. Left open because I want to inspect work.
JD1 SCOTT	16-004	2016-04-19	Tyrone	9			Needs cleaning of vegetation in the channel, ditch was inspected from 169 to hwy 19, pictures show a multiple problem areas and vegetation restricting flow in the channel	Selly		9/22/2016	12/15/2016	\$ 42,723.48	cleaning and culvert installed. Selly needs to touch up the culvert with more fill. Will need to be inspected spring.
JD4 SCOTT	16-031	2016-10-11	Tyrone	2	HARDWICK,ALDEN E & MARY M	Randy Oldenberg	Look for blockage	SK truck & Excavating		10/27/2016	12/15/2016	\$ 4,330.00	Spot cleanout finished. Need to add Shannon Kotasek to DDB. Needs inspection.
JD4 SCOTT	16-058	2016-12-12	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.
JD5 RICE	17-002	2017-01-03	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.
JD15 BE	17-008	2017-02-16	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500				needs inspection.

■ = New inquiries within the last 2 months that have not been looked into.

■ = Closed projects that have been inspected and paid for work done.

White= projects that are in progress, they are currently being worked on and still have issue that need to be done.

■ = Projects that are in review, they are projects that have to be looked into or are being set aside for future work.