



---

# **Le Sueur County, MN**

**Tuesday, June 6, 2017**

**Board Meeting**

## **Item 6**

**9:25 a.m. Nik Kadel, Ditch Inspector (15 minutes)**

**Staff Contact:**

Le Sueur County Ditch Report: 4/1/17 ■ =New ■ =Closed white=current ■ = In Review

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD2	17-034	5/12/2017	Sharon	14	Christian Family LP	Arlen Krugerud	Culvert holding water and flooding corner of of farm land.						Planting 5/13/17, need to wait till fall to get work done.
CD6	16-057	10/10/2016	Montgomery	17	VLASAK FARMS		culvert needs to be installed	selly		10/10/2016	12/10/2016	\$ 8,398.56	spot cleaning was done, need meeting with selly.
CD6	16-028	10/4/2016	Montgomery	7	RYNDA, WILLIAM J	Jerry Selly	Culvert Replacements (2) on each end of the line, the work is done, this is for follow up repairs.	Selly		10/4/2016	12/1/2016	\$ 18,610.00	Selly did cleaning and came back to do repairs on culvert. These are to different repairs tied to one project on CD6.
CD15	16-033	10/18/2016	Kilkenny	22	MCGILLEN, JOHN E & PAMELA K	MCGILLEN, JOHN E & PAMELA K		Barnette		12/23/2016			Barnettes will be removing beaver dams.
CD15	17-011	3/24/2017	Kilekenny	22	McGILLEN, JOHN E & PAMELA K	mcGILLEN, JOHN E & PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017			Need to site inspection to check on progress.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA, BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES, JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA, BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Waiting for dnr permits
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD22	16-062	12/30/2016	Montgomery	10	SENECA FOODS CORP	Chris Reomhell	Needs to be checked out, wants cleaning done before or by spring. Needs to be checked with county.	Selly	N/A	2/1/2017		\$ -	The city of Montgomery is in charge of this ditch
CD23	16-024	9/29/2016	Lexington	20	WIELAND, ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch spection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for marks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.

Le Sueur County Ditch Report: 4/1/17 ■ =New ■ =Closed white=current ■ = In Review

CD28	17-023	4/26/2017	Derrynane	10	Woestehoff, David J & Krista	Woestehoff, David j & Krista	Collapsing culvert, cannot safely get equipment over crossing.	Selly		5/17/2017			Inspected and waiting for Selly adive to see if he can save culvert or if we have to order a new one.
CD31	16-055	12/5/2016			JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						needs inspection once snow melts.
CD36	17-001	1/3/2017	Elysian	3	SPRAGUE,JOHN & LISA	jack sprague	The control structure in which the ditch runs through needs to be checked out once the water is on a low point.						needs inspection once water drops to check structure.
CD37	17-020	4/24/2017	Cleveland	7	Dickie & Ellen Graydon	Robert Krenik	General ditch cleanout starting from last falls.	Zimmerman	N/A	5/4/2017	5/12/2017	\$ 9,585.00	Ditch is cleaned and everything looks good!
CD38	17-010	3/23/2017	Kilkenny	26	Braun, Josephine ann	Jerome Miller	Water backing up along a few culverts back in the wetlands.						Did an inspection and found that 2 culverts need to be repaired immediately. However it will be tough for equipment to operate and it will have to be colder to do work. Need to find a contractor.
CD38	16-053	11/30/2016	Kilkenny	27	STANGLER FAMILY FARM LLC	STANGLER FAMILY FARM LLC	Remove 2 culverts that are restricting flow. Stangler also wants remove the crossing. He says he can get a contractor to do the work for cheaper.						This is at landowner cost. Need to keep in contact just to see what he does. The county will not pay for it. Culverts are removed needs a quick drive by.
CD40	16-061	42725	Montgomery	22	BAUER,LEROY O & BONNIE	BAUER,LEROY O & B	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Has been inspected, needs more investigation and more work for the future.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL,DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER,DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD40	17-003	1/4/2017	Montgomery	28	WENKER,JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	7000				in progress

Le Sueur County Ditch Report: 4/1/17 ■=New ■=Closed white=current ■= In Review

CD41	17-013	3/31/2017	Lexington	30	Beers	Jerry Cooney	Tile Holding back water. Needs to be replaced or fixed.	Selly		3/31/2017		\$ 6,306.30	Tile inlet by the road was cleaned and water was drained, it will be a tile project for the future.
CD43	17-007	2/3/2017	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake						OWL is being determined by the DNR. We have to hold off work until we have word from them.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-045	42690	Lanesburgh	20	STELLA, MICHAEL J & SHIRLEY A		LO has requested that the ditch crossing be repaired.	Selly		4/28/2017			Culvert has been inspected and culvert has been ordered. Waiting for dry weather to install.
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						
CD44	16-038	11/1/2016				Rusty Tiede	Collapsed culvert	Braith Excavating		11/1/2016	12/7/2016	\$ 1,445.00	done
CD45	16-048	11/21/2016	Derrynane	33	BLASCHKO, DANIEL L	BLASCHKO, DANIEL L	sloughing 40 yards from road. NE side of 221						will have to be checked east of shae lake for repairs.
CD45	17-028	5/8/2017	Derrynane	33	DNR Real Estate MGT	Rusty Tiede	Beaver Dams back along shae lake in the county ditch.			5/16/2017			I have got a DNR beaver permit and trapper to catch the beaver first before I move to have the dams cleaned.
CD45	17-029	42883	Derrynane	34	Binczik, Dianne C	Rusty Tiede	Culvert crossing is being washed out, culvert is good but crossing is	Selly		42872			Selly is going to get me an estimate on what it will cost to repair the culvert.
CD46	16-060	2016-12-13	Montgomery	28	PICKA FAMILY FARM TRUST	PICKA FAMILY FARM TRUST	A crossing has been eroding away and needs repair.						Came in about crossing eroding away, talked to havel about fixing it when he is working on the CD40 crossing.

Le Sueur County Ditch Report: 4/1/17 ■=New ■=Closed white=current ■= In Review

CD46	16-025	2016-09-29	Montgomery	28	KRAUTKREMER, GENE O & LINDA C		Culvert in Disrepair. Rotting out.	Havel					Talked to Havel, he said he has not had time to replace culvert. Will get to it this spring.
CD47	16-043	11/14/2016	Cleveland	19			Apply for DNR Public Water Permit to clean out into the cattails. All work north of HWY 99 will take place once permit is approved.	Zimmerman		4/28/2017	5/16/2017	\$ 1,485.00	Zimmerman has cleaned the ditch and bill has been sent to court house.
CD48	16-032	10/14/2016	Montgomery	6	AUGST, NORMAN A & PATRICIA	Brian Rynda	Culvert for field crossing is rusted out and collapsing	Braith Excavating		10/14/2016	12/21/2016	\$5,270.90	
CD51	17-006	2/2/2017				Anthony Beers	Check to see if needs ditch cleaning						need inspection.
CD53	17-032	5/12/2017	Lexington	17	Erkel, Floyd & Ellen	Erkel, Floyd & Ellen	Needs ditch clean out, thinking something could be holding water futher up the ditch.	Zimmerman		5/12/2017		\$ 9,135.00	Ditch cleaned. Future work further up ditch?
CD58	17-012	3/28/2017	Cleveland	34	Steve Matejcek	Steve Matejcek	Wants ditch cleaned all the way to the lake.						Holding off work.
CD58	17-018	4/19/2017	Cleveland	29	Struck, Gerald A	Lynn Loeffler	Slough in ditch holding back water, a stuck prop?						Holding off work.
CD59	16-017	9/23/2016	Elysian	3	DOMONOSKE, DONALD & JUDY	Donald Domonoske		Zimmerman		10/3/2016	11/21/2016	\$ 6,240.00	Work has been finished and paid for. This was left in progress because more calls about different parts needing cleaning.
CD59	16-018	2016-09-23	Elysian	11	QUAST, MILO & VIVIAN	Donald Domonoske	Sloughs and build a diversion on the east end to the waterway on co. hwy 7.	Zimmerman		9/23/2016	12/7/2016	\$6,240.00	
CD59	17-014	4/3/2017	Elysian	9	QUAST, MILO & VIVIAN	Curt Ballman	Ditch cleaning	Zimmerman		4/28/2017	5/26/2017	\$ 1,710.00	Ditch had a lot of sediment from land owner who requested cleaning. Needs buffers and different practices.
CD60	17-031	5/9/2017	Cordova	18	Ebert, Nathan J	Lloyd Tiede	Large ditch cleaning and water backing up on to farm land.	Zimmerman	\$17,000.00	5/9/2017	5/30/2017	\$ 23,155.00	Letters have been sent out and we are working with land owners to get the ditch cleaned before planting season.

Le Sueur County Ditch Report: 4/1/17 ■=New ■=Closed white=current ■= In Review

CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017			Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!
CD61	17-021	4/21/2017	Cordova	23	McGILLEN,JOHN E & PAME	David Novotny	Tile Holding back water. Needs to be replaced or fixed.						Needs to be inspected to find problems.
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.						needs inspection. Holding off work
CD64	17-024	4/28/2017	Cordova	17	Moudry, James	Melvin Schley	Ditch needs cleaning, had a few land owners come in and inspected the ditch futher.	zimmerman		4/28/2017	5/20/2017	\$ 6,435.00	Ditch cleaned! Spoils spread!
CD68	17-028	5/4/2017	Cordova	27	Novotny, Marvin G	Roger Hoenstadt	past ditch work not seeding and a inlet being washed out.						Needs an inspection.
CD70	16-026	9/29/2016	Tyrone	16	O'BRIEN,MARY GRACE	Dale Kessler	Sediment and vegetation has built up and ditch needs cleaning.	Selly	22260	9/29/2016	12/12/2016	\$ 45,177.30	Work has been finished and he has been paid for. Left open because I want to inspect work.
JD1 SCOTT	16-004	4/19/2016	Tyrone	9			Needs cleaning of vegetation in the channel, ditch was inspected from 169 to hwy 19, pictures show a multiple problem areas and vegetation restricting flow in the channel	Selly		9/22/2016	12/15/2016	\$ 42,723.48	cleaning and culvert installed. Selly needs to touch up the culvert with more fill. Will need to be inspected spring.
JD4 SCOTT	16-031	10/11/2016	Tyrone	2	HARDWICK,ALDEN E & MARY M	Randy Oldenberg	Look for blockage	SK truck & Excavating		10/27/2016	12/15/2016	\$ 4,330.00	Spot cleanout finished. Need to add Shannon Kotasek to DDB. Needs inspection.
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.
JD4 SCOTT	17-025	4/28/2017	Derrynane	6	Schwartz, Leroy J & Patricia		Branch K tile is collapsed is 2 places and needs to be repaired.	Selly	13125	4/25/2017			Selly is working on repairing the tile.

JD4 SCOTT	17-026	4/4/2017	Derrynane	5	Neisen, Albertus & Elizabeth		There are a lot of complaints about tile blockages and flow.	Selly and Empire PipeServices		4/12/2017	4/24/2017	\$ 5,903.00	Did a Tile Televising and Nothing went to plan. Water was too high and too murky to get a good view. So I cut it early. I suggest doing this in the fall before the snowfall and less water.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500				Ditch has had inspection and found out that there is a joint survey going on. Waiting for redetermination and survey to be done.