



Le Sueur County, MN

Tuesday, October 3, 2017

Board Meeting

Item 4

9:10 a.m. Nik Kadel, Ditch Inspector (15 min)

RE: Ditch Update

Staff Contact:

Le Sueur County Ditch Report: 9/1/17 ■ =New ■ =Closed ■ =current ■ = In Review

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD15	16-033	10/18/2016	Kilkenny	22	MCGILLEN,JOHN E & PAMELA K	MCGILLEN,JOHN E & PAMELA K		Barnette		12/23/2016			Barnettes will be removing beaver dams.
CD15	17-011	3/24/2017	Kilekenny	22	McgiLLEN,JOHN E & PAMELA K	mcGILLEN,JOHN E & PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017			Need to site inspection to check on progress.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Waiting for dnr permits
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD22	16-062	12/30/2016	Montgomery	10	SENECA FOODS CORP	Chris Reomhell	Needs to be checked out, wants cleaning done before or by spring. Needs to be checked with county.	Selly	N/A	2/1/2017		\$ -	The city of Montgomery is in charge of this ditch
CD23	16-024	9/29/2016	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch spection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for marks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD23	17-042	7/24/2017	Lexington	14	David, William B	David, William B	Culvert and crossing condition and history.						4.5 diameter culvert, landowner wants to extend the culvert, will have to wait until crops come off to have project done.
CD26	17-039	42912	Lexington	30	BlaSCHKO,DANIEL L	Henery Macho/ operator mike	Ditch clean	Shannon Kotasek					fall cleanout once crops are off

Le Sueur County Ditch Report: 9/1/17 ■ =New ■ =Closed white=current ■ = In Review

CD28	17-023	4/26/2017	Derrynane	10	Woestehoff, David J & Krista	Woestehoff, David j & Krista	Collapsing culvert, cannot safely get equipment over crossing.	Selly		5/17/2017			waiting until crops are off to do this project.
CD29	17-035	6/1/2017	Derrynane	16	Merger, Richard M & Lori A	Merger, Richard M & Lori A	Culvert that was done last year started settling and thinks it needs more dirt.	Selly			8/1/2017		Selly put a few loads of dirt to level off the culvert!
CD31	16-055	42709			JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						I inspected this and water seems to be flowing fine. CD44 will need cleaning in a year or two.
CD34	17-037	6/26/2017	Sharon	11	Tiede, Dale L & Patrica Ann	Tiede, Dale L & Patrica Ann	Needs general cleaning, sloughs and nees inspection north of the area too.						Needs inspection for fall cleanout.
CD38	17-010	42817	Kilkenny	26	Braun, Josephine ann	Jerome Miller	Water backing up along a few culverts back in the wetlands.	Zimmerman	\$21,000	Jul-17	8/25/2017	\$ 22,445.00	Replaced 3 culverts and reshaped spur 3. and cleaned the main ditch. Still have to seed the CRP.
CD40	16-061	42725	Montgomery	22	BAUER,LEROY O & BONNIE	BAUER,LEROY O & BONNIE	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Has been inspected, needs more investigation and more work for the future.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL,DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER,DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD40	17-003	1/4/2017	Montgomery	28	WENKER,JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	7000				in progress
CD43	17-007	2/3/2017	Lexington	21	MORAVEC,JACQUELYN M		water not being able to get into Tyler lake						OWL is being determined by the DNR. We have to hold off work until we have word from them.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE,RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems

Le Sueur County Ditch Report: 9/1/17 ■ =New ■ =Closed ■ =current ■ = In Review

CD44	16-045	42690	Lanesburgh	20	STELLA,MICHAEL J & SHIRLEY A		LO has requested that the ditch crossing be repaired.	Selly		4/28/2017	8/1/2017	\$3,175	Culvert has been installed and inspected and invoice has been paid.
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN,BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						
CD45	16-048	11/21/2016	Derrynane	33	BLASCHKO,DANIEL L	BLASCHKO,DANIEL L	sloughing 40 yards from road. NE side of 221						will have to be checked east of shae lake for repairs.
CD45	17-029	42883	Derrynane	34	Binczik, Dianne C	Rusty Tiede	Culvert crossing is being washed out, culvert is good but crossing is too small to get equipment across. Culvert is inverted 6inches from elevation shots taken. Needs to be put back to level grade.	Bids?					Taking bids from contractors for a clean out from marys lake to shae lake. This includes the culvert and the cleaning.
CD46	16-060	2016-12-13	Montgomery	28	PICKA FAMILY FARM TRUST	PICKA FAMILY FARM TRUST	A crossing has been eroding away and needs repair.						Came in about crossing eroding away, talked to havel about fixing it when he is working on the CD40 crossing.
CD46	16-025	2016-09-29	Montgomery	28	KRAUTKREMER,GENE O & LINDA C		Culvert in Disrepair. Rotting out.	Havel					Havel said he will install culvert this fall.
CD51	17-036	6/13/2017	Cordova	5	Schloesser, Michael & Darcey	Schloesser, Michael & Darcey	Crossing and road culvert being washed out.	Selly		8/1/2017	9/1/2017	\$6,159	Culvert installed, land owner ordered and extention and paid for it!
CD51	17-006	2/2/2017				Anthony Beers	Check to see if needs ditch cleaning						need inspection. Needs cleaning.
CD53	17-038	6/26/2017	Lexington	7	Mager, Clarence A & Debra J	Dale tiede	Ditch cleaning and culvert removal	Zimmerman?					needs inspection and fall clean, would like zimmerman to do cleaning.
CD58	17-012	3/28/2017	Cleveland	34	Steve Matejcek	Steve Matejcek	Wants ditch cleaned all the way to the lake.						Got the go ahead to clean to lake henry for fall! clean! Need contractor and send out letters to land owners.
CD58	17-018	4/19/2017	Cleveland	29	Struck, Gerald A	Lynn Loeffler	Slough in ditch holding back water, a stuck prop?						Holding off work.

Le Sueur County Ditch Report: 9/1/17 ■ =New ■ =Closed white=current ■ = In Review

														Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!
CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017				
CD61	17-021	4/21/2017	Cordova	23	McGILLEN,JOHN E & PAME	David Novotny	Tile Holding back water. Needs to be replaced or fixed.							having ISG make ann engeneering report for the county to replace couty tile.
CD61	17-046	9/11/2017	Cordova	23	McGILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.							needs inspection
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.							needs inspection. Holding off work
JD1 SCOTT	16-004	4/19/2016	Tyrone	9			Needs cleaning of vegetation in the channel, ditch was inspected from 169 to hwy 19, pictures show a multiple problem areas and vegetation restricting flow in the channel	Selly		9/22/2016	12/15/2016	\$ 42,723.48		Culvert was touched up and fixed.
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out							Needs inspection this spring.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.							needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500					Ditch has had inspection and found out that there is a joint survey going on. Waiting for redetermination and survey to be done.