

Le Sueur County, MN

Tuesday, December 12, 2017

Board Meeting

Item 3

9:10 a.m. Nik Kadel, Ditch Inspector (10 min)

RE: Ditches Update

Staff Contact:

											Droject		
Drainage	DB Renair#	Date Received	Townshin	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
Drainage	рв керап #	Date Received	TOWNSHIP	Section	Landowner	керап	Problem/Proposed Work				Date		Barnettes will be
					MCCULEN IOUN F 0	MCCHLEN IOUNE							removing beaver
CD45	46.022	40/40/2046	IZH		MCGILLEN,JOHN E &	MCGILLEN,JOHN E				42/22/2046			dams. While they
CD15	16-033	10/18/2016	Kiikenny	22		& PAMELA K		Barnette		12/23/2016	<u> </u>		clean the ditch.
CD4F	17.011	2/24/2047	Wil a lease see	22	Mcgillen,JOHN E &	mcGILLEN,JOHN E &		D + + -	5050	4/4//2047			Waiting for them to
CD15	17-011	3/24/2017	Kilekenny	22	PAMELA K	PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017			clean it out.
CD4C	16.027	44/4/2046		10	TDINIKA DETTV		Colorest in failing and a field assistant						Culvert needs cleaning
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						around it
CD4C	16.040	44/2/2046	Laudinahan	12	ANYTEC IANAEC I O DUTII A		clean out to the lake. Need DNR permits to proceed. Water control						waiting on DNR water
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		structure?						permit
60.46	16.011	44/2/2046		4.0					20566.4				Waiting for dnr
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				permits
		. /2= /20.4		•									Sent letters, no
CD21	16-007	4/25/2016	Lexington	28	3	Joe Schloesser	washing out next to culvert in driveway						response
													Did a ditch inspection
													on about half the
													ditch. It's going to
													need a lot of work and
													a redetermination.
													Having a meeting with
					WIELAND,ROBERT A &								board about how to
CD23	16-024	9/29/2016	Lexington	20	CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						proceed.
							Don Westerman wants the outlet structure for marks lake repaired						
							before any ditch clean out takes place. Site needs to be visited and						drop inlet structure
CD23	16-044	11/14/2016				Don Westerman	photos taken winter of 2016-17.						needs replacment.
													4.5 diameter culvert,
													landowner wants to
													extend the culvert, will
													have to wait until
													crops come off to have
CD23	17-042	42940	Lexington	14	David, William B	David, William B	Culvert and crossing condition and history.	Selly					project done.
						Henery Macho/		Shannon					fall cleanout once
CD26	17-039	42912	Lexington	30	BlaSCHKO,DANIEL L	I -		Kotasek		11/1/2017			crops are off
					Woestehoff, David J &	Woestehoff, David j							
CD28	17-023	4/26/2017	Derrynane	10	Krista	& Krista	Collapsing culvert, cannot safely get equipment over crossing.	Selly		5/17/2017	11/30/2017	\$ 5.980.00	finished.
	323	., 20, 2017	_ c y.idiic	10			The second secon			0,11,2011	22,30,2017	7 3,300.00	I inspected this and
													water seems to be
													flowing fine. CD44 will
													need cleaning in a year
CD31	16-055	42709			JAHN,BRIAN C FAMILY LP	iohn Widmer	where 31 and 44 meet is clogged with grass.						or two.
CD31	10 000	42703			JATIN, BRIAN CTANIET EF	John Widiner	micro of and 44 micerio ciogged with grass.						or two.

Le Sue	ur Count	y Ditch Re	port: 12	/1/17	=New ==Close	ed white=curre	ent == In Review					
CD34	17-037	6/26/2017	Sharon	11	Tiede, Dale L & Patrica Ann	Tiede, Dale L & Patri	Needs general cleaning, sloughs and nees inspection north of the area too.	Zimmerman		10/20/2017	10/28/2017	cleaned from the road north of Pioneer power all the way south.
CD38	17-010	42817	Kilkenny	26	Braun, Josephine ann	Jerome Miller	Water backing up along a few culverts back in the wetlands.	Zimmerman	\$21,000	Jul-17	8/25/2017	Replaced 3 culverts and reshaped spur 3. and cleaned the main ditch. Still have to seed the CRP.
CD40	16-061	42725	Montgomery	22	BAUER,LEROY O & BONNIE	BAUER,LEROY O & BONNIE K	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch					Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL,DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water					Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER,DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel				Land was too wet to finish cleaning by havel.
CD40	17-003	1/4/2017	Montgomery	28	WENKER,JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	7000			in progress
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water siting in the field not draining in the culvert.					Tile collapsed, having it looked at by ISG and a meeting on Dec. 7th
	17-007		Lexington		MORAVEC,JACQUELYN M	, ,	water not being able to get into Tyler lake					Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE,RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.					CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN,BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.					
CD45	16-048	42695	Derrynane	33	BLASCHKO,DANIEL L	BLASCHKO,DANIEL L	sloughing 40 yards from road. NE side of 221	zimmerman				being taken care of during the zimmerman clean.
CD45	17-029		Derrynane			Rusty Tiede		zimmerman				Taking bids from contractors for a clean out from marys lake to shae lake. This includes the culvert and the cleaning.
CD45	17-050	11/17/2017	Derrynane	26	Binczik, Thomas	Binczik, Thomas	Beaver dam blocking up a culvert.	Selly				

Le Su	eur Coun	ty Ditch Re	eport: 12/	/1/17	=New ==Close	ed white=curre	ent == In Review						
													this is all Cd45 project put into one. So this is
							Ditch clean, beaver dame removal, culvert lower/ crossing repair						the price for all the
CD45	17-047	10/3/2017	Lexington		Tiede, Leroy & doris	<u> </u>	and sloughing repair.	Zimmerman	\$ 22,910.00	11/20/2017	12/1/2017		projects of CD45.
CD4C	16.025	2016 00 20	Montgomony		KRAUTKREMER,GENE O &		Culvert in Disconnin Botting out	Herrel					culvert installed need
CD46	16-025	2016-09-29	Montgomery	28	LINDA C		Culvert in Disrepair. Rotting out.	Havel					invoice. need invoice, partially
CD51	17-006	2/2/2017	Cordova	5	Rich acres inc	Anthony Beers/ Mike	Check to see if needs ditch cleaning	Selly	\$ 17,000.00	11/1/2017			paid.
		, , ,					g	,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , -			Cleaned the entire
					Mager, Clarence A &								ditch and pulled a
CD53	17-038	6/26/2017	Lexington	7	Debra J	Dale tiede	Ditch cleaning and culvert removal	Zimmerman		11/1/2017	11/18/2017	\$ 20,025.00	
													We have a trapper out
CDEZ	17.051	42000	IX:II.amm.	l	Brockway, Richard &	•	Beaver dams and beaver problems, going to trapp before clearing	Dellings					ther along the ditch
CD57	17-051	43069	Kilkenny	3	kathleen	& Kathleen	dams.	Rollings					now. Got the go ahead to
													clean to lake henry for
													falll clean! Need
													contractor and send
								Shannon					out letters to land
CD58	17-012	3/28/2017	Cleveland	34	Steve Matejcek	Steve Matejcek	Wants ditch cleaned all the way to the lake.	Kotasek					owners.
													cleaned part of ditch
								Shannon					and removed
CD58	17-018	4/19/2017	Cleveland	29	Struck, Gerald A	Lynn Loeffler	Slough in ditch holding back water, a stuck prop?	Kotasek					obstruction.
													This stretch was attempted last year
													but it was too wet.
													Land owner asked for
					Domonoske, Donald &	Domonoske, Doanld	Asked about this same are again, will have to inspect in the spring						it to be looked at
CD59	16-017	9/23/2016	Elysian		Judy	& Judy	for a clean out.						again. 10/2017
													Staightened the
													culvert to the county
													ditch so there wont be
							Steel culvert has been eroding away and needs to be straightened						such a huge bank.
							for the county ditch. Also the cement bindings have broke apart						Installed bindings on the cement part so it
CD60	17-049	8/25/2017	Cleveland	2	McCabe, Barbara		which have created a big sink hole near the highway 99.	Selly		11/1/2017	11/20/2017		wont come apart.
CD00	1, 545	5,25,2017	Cicvelana		modube, burburu		minor nate of cated a significance field the fighway 55.	Jeny		11/1/201/	11/20/2017	y 10,070.10	none come apart.
													Traxler Thinks the
													problem is the tile in
													the easment land on
													the Mcgillen land. Will
							Find where the tile has been plugged or blown out, repair that area						have to look into it in
							to get water flowing again, were told to get a cost estimate before			- 15 t			the future. Waiting on
CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	work could be done	Pat Traxler		3/31/2017			invoice!

Le Sue	ur Count	ty Ditch Re	port: 12,	/1/17	=New ==Close	ed white=cur	rent == In Review						
CD61	17-021	4/21/2017	Cordova	23	Mcgillen,JOHN E & PAME	David Novotny	Tile Holding back water. Needs to be replaced or fixed.						having ISG make an engeneering report for the county to replace couty tile.
CD61	17-046	9/11/2017	Cordova	23	Mcgillen,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.						Did inspection waiting until after meeting to do work.
CD62	17-040	7/11/2017	Lanesburgh	15	Picha, Constance	Jeff Landsberg	Crossing washing out from culvert starting at railroad.	selly		7/11/2017	11/20/2017	\$ 3,690.00	needs inspection.
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.						Holding off work
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.
JD5 RICE		1/3/2017			SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500				Ditch has had inspection and found out that there is a joint survey going on. Waiting for redeterminationation and survey to be done.