



Le Sueur County, MN

Tuesday, February 6, 2018

Board Meeting

Item 4

9:10 a.m. Nik Kadel, Ditch Inspector (10 min)

RE: Ditch Update

Staff Contact:

Le Sueur County Ditch Report: 2/1/18 ■ =New ■ =Closed white=current ■ = In Review

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD15	16-033	10/18/2016	Kilkenny	22	MCGILLEN,JOHN E & PAMELA K	MCGILLEN,JOHN E & PAMELA K		Barnette		12/23/2016			Barnettes will be removing beaver dams. While they clean the ditch.
CD15	17-011	3/24/2017	Kilekenny	22	McGILLEN,JOHN E & PAMELA K	mcGILLEN,JOHN E & PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017			Waiting for them to clean it out.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	Selly?	20566.4				Waiting for dnr permits
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD23	16-024	9/29/2016	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for marks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD23	17-042	42940	Lexington	14	David, William B	David, William B	Culvert and crossing condition and history.	Selly					4.5 diameter culvert, landowner wants to extend the culvert, will have to wait until crops come off to have project done.
CD26	17-039	42912	Lexington	30	BlaSCHKO,DANIEL L	Henery Macho/ operator mike	Ditch clean	Shannon Kotasek		11/1/2017		\$ 7,420.60	fall cleanout once crops are off
CD28	17-023	4/26/2017	Derrynane	10	Woestehoff, David J & Krista	Woestehoff, David j & Krista	Collapsing culvert, cannot safely get equipment over crossing.	Selly		5/17/2017	11/30/2017	\$ 5,980.00	finished.
CD31	16-055	42709			JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						I inspected this and water seems to be flowing fine. CD44 will need cleaning in a year or two.

Le Sueur County Ditch Report: 2/1/18 ■=New ■=Closed white=current ■= In Review

CD34	17-037	6/26/2017	Sharon	11	Tiede, Dale L & Patrica Ann	Tiede, Dale L & Patrica	Needs general cleaning, sloughs and nees inspection north of the area too.	Zimmerman		10/20/2017	10/28/2017	\$ 10,305.00	cleaned from the road north of Pioneer power all the way south.
CD38	17-010	42817	Kilkenny	26	Braun, Josephine ann	Jerome Miller	Water backing up along a few culverts back in the wetlands.	Zimmerman	\$21,000	Jul-17	8/25/2017	\$ 22,445.00	Replaced 3 culverts and reshaped spur 3. and cleaned the main ditch. Still have to seed the CRP.
CD40	16-061	42725	Montgomery	22	BAUER, LEROY O & BONNIE	BAUER, LEROY O & BONNIE K	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL, DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER, DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD40	17-003	1/4/2017	Montgomery	28	WENKER, JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	7000				in progress
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water siting in the field not draining in the culvert.						Tile collapsed, having it looked at by ISG and a meeting on Dec. 7th
CD43	17-007	2/3/2017	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake						Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						
CD45	16-048	42695	Derrynane	33	BLASCHKO, DANIEL L	BLASCHKO, DANIEL L	sloughing 40 yards from road. NE side of 221	zimmerman					being taken care of during the zimmerman clean.
CD45	17-029	42883	Derrynane	34	Binczik, Dianne C	Rusty Tiede	Culvert crossing is being washed out, culvert is good but crossing is too small to get equipment across. Culvert is inverted 6 inches from elevation shots taken. Needs to be put back to level grade.	zimmerman					This was done with the zimmerman project.
CD45	17-050	11/17/2017	Derrynane	26	Binczik, Thomas	Binczik, Thomas	Beaver dam blocking up a culvert.	Selly				\$ 5,452.50	

Le Sueur County Ditch Report: 2/1/18 ■ =New ■ =Closed white=current ■ = In Review

CD45	17-047	10/3/2017	Lexington	3	Tiede, Leroy & doris	Rusty Tiede	Ditch clean, beaver dame removal, culvert lower/ crossing repair and sloughing repair.	Zimmerman	\$ 22,910.00	11/20/2017	12/1/2017	\$ 22,910.00	this is all Cd45 project put into one. So this is the price for all the projects of CD45.
CD46	16-025	2016-09-29	Montgomery	28	KRAUTKREMER,GENE O & LINDA C		Culvert in Disrepair. Rotting out.	Havel					culvert installed need invoice.
CD51	17-006	2/2/2017	Cordova	5	Rich acres inc	Anthony Beers/ Mike	Check to see if needs ditch cleaning	Selly	\$ 17,000.00	11/1/2017	11/26/2017	\$ 18,835.00	need invoice, partially paid.
CD53	17-038	6/26/2017	Lexington	7	Mager, Clarence A & Debra J	Dale tiede	Ditch cleaning and culvert removal	Zimmerman		11/1/2017	11/18/2017	\$ 20,025.00	Cleaned the entire ditch and pulled a culvert.
CD57	17-051	43069	Kilkenny	3	Brockway, Richard & kathleen	Brookway, Richard & Kathleen	Beaver dams and beaver problems, going to trapp before clearing dams.	Rollings					We have a trapper out ther along the ditch now.
CD58	17-012	3/28/2017	Cleveland	34	Steve Matejcek	Steve Matejcek	Wants ditch cleaned all the way to the lake.	Shannon Kotasek				\$ 2,148.25	Got the go ahead to clean to lake henry for fall clean! Need contractor and send out letters to land owners.
CD58	17-018	4/19/2017	Cleveland	29	Struck, Gerald A	Lynn Loeffler	Slough in ditch holding back water, a stuck prop?	Shannon Kotasek				\$ 1,218.10	cleaned part of ditch and removed obstruction.
CD59	16-017	9/23/2016	Elysian	3	Domonoske, Donald & Judy	Domonoske, Doanld & Judy	Asked about this same are again, will have to inspect in the spring for a clean out.						This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017
CD60	17-049	8/25/2017	Cleveland	2	McCabe, Barbara		Steel culvert has been eroding away and needs to be straightened for the county ditch. Also the cement bindings have broke apart which have created a big sink hole near the highway 99.	Selly		11/1/2017	11/20/2017	\$ 18,078.10	Staightened the culvert to the county ditch so there wont be such a huge bank. Installed bindings on the cement part so it wont come apart.
CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017			Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!

Le Sueur County Ditch Report: 2/1/18 ■=New ■=Closed white=current ■= In Review

CD61	17-021	4/21/2017	Cordova	23	McGILLEN,JOHN E & PAMELA	David Novotny	Tile Holding back water. Needs to be replaced or fixed.							having ISG make an engineering report for the county to replace county tile.
CD61	17-046	9/11/2017	Cordova	23	McGILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.							Did inspection waiting until after meeting to do work.
CD62	17-040	7/11/2017	Lanesburgh	15	Picha, Constance	Jeff Landsberg	Crossing washing out from culvert starting at railroad.	selly		7/11/2017	11/20/2017	\$ 3,690.00	Problems with railroad, crossing washed out, just replace county culvert and seperated it from railroad.	
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.						needs inspection. Holding off work	
CD64	17-053	12/13/2017	Cordova	20	Chadderdon, Orbbe	Norman Schmidt	Beaver dams blocking up ditch						I have ran parts of this ditch and could not find any dams. I will run the ditch this spring.	
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.	
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of killkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.	
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman				5500	Ditch has had inspection and found out that there is a joint survey going on. Waiting for redetermination and survey to be done.	