



---

# **Le Sueur County, MN**

**Tuesday, April 3, 2018**

**Board Meeting**

## **Item 3**

**9:10 a.m. Nik Kadel, Ditch Inspector (10 min)**

*RE: Ditch Update*

Staff Contact:

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD15	16-033	10/18/2016	Kilkenny	22	MCGILLEN,JOHN E & PAMELA K	MCGILLEN,JOHN E & PAMELA K		Barnette		12/23/2016			dams were removed and beavers were trapped!
CD15	17-011	3/24/2017	Kilekenny	22	McgiLLEN,JOHN E & PAMELA K	mcGILLEN,JOHN E & PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017			Ditch still needs to be cleaned, it was too cold before work could be done.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Starting meetings with DNR!!!!
CD18	18-001	3/26/2018	Montgomery	13	Beatty, Leonard E	Beatty Leonard E	Spoils not spread from past clean out.						Was able to inpect Leonards land and the spoils need to be spread, will need to run the whole ditch.
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD23	16-024	9/29/2016	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for marks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD23	17-042	42940	Lexington	14	David, William B	David, William B	Culvert and crossing condition and history.	Selly					4.5 diameter culvert, landowner wants to extend the culvert, will have to wait until crops come off to have project done.
CD31	17-052	12/12/2017	Derrynane	13	Hoefs, Johns J	Dennis Dietz	Water not flowing through						Needs inspection this spring.
CD31	16-055	42709	derrynane		JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						I inspected this and water seems to be flowing fine. CD44 will need cleaning in a year or two.
CD38	17-054	12/21/2017	Kilkenny	36	Miller, Jerome A	Kenneth Wetzel	Need elevation shots on a culvert, Landowner believes culvert is too high.						Need to get elevation shots!

CD40	16-061	42725	Montgomery	22	BAUER, LEROY O & BONNIE	BAUER, LEROY O & BONNIE K	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL, DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER, DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD40	17-003	1/4/2017	Montgomery	28	WENKER, JOHN D & THERESA	Krautkramer	needs ditch clean out	Havel	\$ 7,000.00	2/1/2017	4/25/2017	\$ 6,037.00	This was done in 2017 and never entered into the report.
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water siting in the field not draining in the culvert.						Tile collapsed, having it looked at by ISG and a meeting on Dec. 7th
CD43	17-007	2/3/2017	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake						Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						
CD54	17-048	10/30/2017	Lanesburgh	11	Ilkka, Gregory M & Judy	Mary Caroline	Tree cloggin a ditch.	Selly					ice block up
CD57	17-051	43069	Kilkenny	3	Brockway, Richard & kathleen	Brookway, Richard & Kathleen	Beaver dams and beaver problems, going to trapp before clearing dams.	Rollings					We have a trapper out ther along the ditch now.
CD59	16-017	9/23/2016	Elysian	3	Domonoske, Donald & Judy	Domonoske, Doanld & Judy	Asked about this same are again, will have to inspect in the spring for a clean out.						This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017
CD61	16-013	9/20/2016	Cordova	23	THEIS, JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017			Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!
CD61	17-021	42846	Cordova	23	McGILLEN, JOHN E & PAMEL	David Novotny	Tile Holding back water. Needs to be replaced or fixed.						having ISG make an engeneering report for the county to replace couy tile.

CD61	17-046	9/11/2017	Cordova	23	McgILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.						Did inspection waiting until after meeting to do work.
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.						needs inspection. Holding off work
CD64	17-053	12/13/2017	Cordova	20	Chadderdon, Orbbe	Norman Schmidt	Beaver dams blocking up ditch						I have ran parts of this ditch and could not find any dams. I will run the ditch this spring.
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500				Ditch has had inspection and found out that there is a joint survey going on. Waiting for redetermination and survey to be done.