



Le Sueur County, MN

Tuesday, August 7, 2018

Board Meeting

Item 3

9:10 a.m. Nik Kadel, Ditch Inspector (10 min)

RE: Update on County Ditches

Staff Contact:

Le Sueur County Ditch Report: 8/1/18 ■ =New ■ =Closed white=current ■ = In Review

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD15	16-033	10/18/2016	Kilkenny	22	MCGILLEN,JOHN E & PAMELA K	MCGILLEN,JOHN E & PAMELA K		Barnette		12/23/2016			dams were removed and beavers were trapped!
CD15	17-011	3/24/2017	Kilekenny	22	McGILLEN,JOHN E & PAMELA K	mcGILLEN,JOHN E & PAMELA K	Asked for a general cleanout around his property.	Barnette	5950	4/1//2017	6/1/2018	\$ 14,245.00	Ditch was cleaned and was inspected. The bills for the beaver dams for the past few years were added together.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Starting meetings with DNR!!!!
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD23	16-024	9/29/2016	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for mareks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD23	18-015	6/19/2018	Lexington	25	Johnson, Gary	Shawn Onken	Collapsed tile not shown on the county maps.	Traxler				\$ 225.00	fixed
CD26	18-012	6/8/2018	Lexington	29	Pioneer builders CO of Nevada	Mike Macho	Landowner thinks has concern that the ditch grade could be off.						I took elevation shots of the ditch.
CD29	18-013	6/11/2018	Derrynane	9	Stuedemann, Kevin	Stuedemann, Kevin	Crossing repair.						wanted to have their own contractor do the work. Have not heard anything from them since.
CD29	18-009	5/22/2018	Derrynane	9	Oconnell, James J	Pat Oconnell	Collapsed tile	Retka tile		5/22/2018	6/8/2018	\$ 888.75	Cement tile cracked mixed with repaired tile in peat ground.
CD31	17-052	12/12/2017	Derrynane	13	Hoefs, Johns J	Dennis Dietz	Water not flowing through						Needs DNR permit to clean through public waters.
CD31	16-055	42709	derrynane		JAHN,BRIAN C FAMILY LP	iohn Widmer	where 31 and 44 meet is clogged with grass.						Needs DNR permit to clean through public waters. Found Culvert in Ditch need to more information.

Le Sueur County Ditch Report: 8/1/18 ■=New ■=Closed white=current ■= In Review

JD38	18-003	4/24/2018	kilkenny	27	Stangler, Richard	Stangler, Richard	Cleanout on Spur 5, Field tile under water.	Zimmerman		5/10/2018	5/24/2018	\$ 6,210.00	Finished clean out. Waiting on invoice for seeding invoice
JD38	18-006	5/4/2018	Kilkenny	25	Houser, Terry W & Bev E	Jim Hebel	Erosion from public waters coming into the county ditch.						Going to get some second opinions before we start repiaring ditch.
JD38	17-054	12/21/2017	Kilkenny	36	Miller, Jerome A	Kenneth Wetzel	Need elevation shots on a culvert, Landowner believes culvert is too high.						Need to get elevation shots!
CD40	16-061	42725	Montgomery	22	BAUER, LEROY O & BONNIE	BAUER, LEROY O & B	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL, DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER, DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water siting in the field not draining in the culvert.						Waiting for the petition on the improvement!
CD43	17-055	12/29/2017	Lexington	15	Holicky, Glenn & Ann	Mark Menke	Crossing repair.	Selly		5/25/2018	7/3/2018	\$ 545.00	Crossing has eroded and cannot get a vehicle across it.
CD43	17-007	2/3/2017	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake						Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						Was inspected, needs a DNR permit to be filled out to be cleaned.
CD51	18-018	7/24/2018	sharon	36	Selly, James	Anothny, Beers	stretch of ditch might have been missed on a past ditch clean out.	Selly					Found two culverts, one crosing needs repair, the other needs to be replaced.
CD54	17-048	10/30/2017	Lanesburgh	11	Ilkka, Gregory M & Judy	Mary Caroline	Tree cloggin a ditch.	Selly		3/1/2018	5/1/2018	\$ 1,580.00	ice block up and tree blocking ditch was removed
CD57	17-051	43069	Kilkenny	3	Brockway, Richard & kathleen	Brookway, Richard & Kathleen	Beaver dams and beaver problems, going to trapp before clearing dams.	Rollings					We have a trapper out ther along the ditch now.
CD59	18-017	7/9/2018	waterville	18	US Fish and Wildlife Service	Jeff Ballman	water backing up, maybe bever dam						need to run whole ditch to find obstruction

Le Sueur County Ditch Report: 8/1/18 ■=New ■=Closed white=current ■= In Review

CD59	16-017	9/23/2016	Elysian		Domonoske, Donald & Judy	Domonoske, Doandl & Judy	Asked about this same are again, will have to inspect in the spring for a clean out.								This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017
CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler			3/31/2017				Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!
CD61	17-021	42846	Cordova	23	McGILLEN,JOHN E & PAMEL	David Novotny	Tile Holding back water. Needs to be replaced or fixed.								having ISG make an engeneering report for the county to replace couly tile.
CD61	17-046	9/11/2017	Cordova	23	McgILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.								Did inspection waiting until after meeting to do work.
CD62	18-010	5/23/2018	Lanesburgh	15	Picha, Constance M	Picha, Constance M	Culvert that was just repaired was washed out because of railroad culvert.	Selly			6/22/2018	7/3/2018	\$ 6,550.75		emergency crossing fix plus adding extra clay and anti seep collar. Waiting for for railroad to contact me back.
CD63	18-007	43228	Montgomery	35	Miller, William A & Marilyn	Doug Miller	Two Culvert Washing out, a road culvert on 141st st and the field crossing.	Kotasak			7/2/2018	7/27/2018	\$ 1,840.00		Inspected, Road culvert is townships responsibility and kotasak will be fixing the field crossing.
CD63	18-004	5/3/2018	Montgomery	36	James Fisher	James fisher	Two culverts, one located on 99 and on located on the fisher land with logs blocking it.								Land owner was concerned about being flooded out by the culvert on 99 that was put in a few years ago. (Found info, Working with HWY DPT)
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.								needs inspection. Holding off work
CD64	18-016	7/9/2018	Cordova	27	Kolander, Leroy	Kolander, Leroy	Slough with tile in it.	Selly			7/29/2018				Slough has taken out the tile.
CD64	18-020	7/27/2018	Cordova	21	DNR Real Estate MGT	Kolander, Leroy	Culvert underwater on highway 11	Selly			7/30/2018				found a beaver dam hokding baack about 3 ft of water.
CD64	17-053	12/13/2017	Cordova	20	Chadderton, Orbbe	Norman Schmidt	Beaver dams blocking up ditch								I have ran parts of this ditch and could not find any dams. I will run the ditch this spring.

Le Sueur County Ditch Report: 8/1/18 ■=New ■=Closed white=current ■= In Review

JD1 Scott	18-005	5/3/2018	Tyrone	2	Kessler, William	Kessler, William	Ersion and sloughing and undercutting.							Looks like his tile might be cause some of his problem on the sloughing part, the ditch bank is mud mid way up next to the tile. Once he fixes his tile we will repair the ditch.
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out							Needs inspection this spring.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.							needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman		5500				Ditch has had inspection and found out that there is a joint survey going on. Waiting for redetermination and survey to be done.