



Le Sueur County, MN

Tuesday, November 27, 2018

Board Meeting

Item 4

9:15 a.m. Nik Kadel, Ditch Specialist (10 min)

RE: Ditch Update

Staff Contact:

Le Sueur County Ditch Report: 12/1/18 ■ =New ■ =Closed white=current ■ = In Review

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD6	18-026	10/1/2018	Montgomery	18	Rynda, William	Richard Kuckaka	Beaver Dams	selly/ Shane Steven's					Trapper has been out there and cleared a few dams.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA, BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES, JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA, BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Starting meetings with DNR!!!!
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD23	18-025	9/21/2018	Lexington	35	Goettl, Robert & Lori A	Goettl, Robert & Lori A	Beaver dams and beaver problems.	selly/ Shane Steven's				\$ 1,270.00	We have a trapper out ther along the ditch now.
CD23	16-024	9/29/2016	Lexington	20	WIELAND, ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for mareks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD29	18-035	10/1/2018	Derrynane	9	O'connell, James J	O'connell, Mike	Replace all tile on his property.						This needs a to be discussed about replacine whole tile line and have ISG take a look.
CD29	18-013	6/11/2018	Derrynane	9	Stuedemann, Kevin	Stuedemann, Kevin	Crossing repair.						wanted to have their own contractor do the work. Have not heard anything from them since.
CD31	17-052	12/12/2017	Derrynane	13	Hoefs, Johns J	Dennis Dietz	Water not flowing through						Needs DNR permit to clean through public waters.
CD31	16-055	42709	derrynane		JAHN, BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						Needs DNR permit to clean through public waters. Found Culvert in Ditch need to more information.
JD38	18-006	5/4/2018	Kilkenny	25	Houser, Terry W & Bev E	Jim Hebel	Erosion from public waters coming into the county ditch.						Going to get some second opinions before we start repiaring ditch.
JD38	17-054	12/21/2017	Kilkenny	36	Miller, Jerome A	Kenneth Wetzal	Need elevation shots on a culvert, Landowner believes culvert is too high.						Need to get elevation shots!

Le Sueur County Ditch Report: 12/1/18 ■ =New ■ =Closed white=current ■ = In Review

CD40	16-061	42725	Montgomery	22	BAUER, LEROY O & BONNIE	BAUER, LEROY O & BONNIE	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch							Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL, DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water							Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER, DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel						Land was too wet to finish cleaning by havel.
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water sitting in the field not draining in the culvert.							Petition was put in!
CD43	17-007	2/3/2017	Lexington	21	MORAVEC, JACQUELYN M		water not being able to get into Tyler lake							Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE, RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.							CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN, BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.							Was inspected, needs a DNR permit to be filled out to be cleaned.
CD45	18-029	11/1/2018	Lexington	2	Miller, Jeff	Dale Tiede	Beaver Dam	Selly/ Shane Steven's						Have a Trapper out there and cleared the Dam.
CD45	18-021	8/7/2018	Derrynane	27	Wacker, Mark	Tom Binzick	Culvert washing out.	Aufderhar					\$ 875.00	Culvert was replaced, waiting on payment from LO.
CD57	17-051	43069	Kilkenny	3	Brockway, Richard & Kathleen	Brookway, Richard & Kathleen	Beaver dams and beaver problems, going to trapp before clearing dams.	Rollings						We have a trapper out there along the ditch now.
CD58	18-030	11/15/2018	Cleveland	29	Struck, Gerald	Lynn Loeffler	Debri in culvert holding back water.							Found a few rocks, looks like culvert will have to be replace. Its starting to rust through.
CD59	16-017	9/23/2016	Elysian	3	Domonoske, Donald & Judy	Domonoske, Doanld & Judy	Asked about this same are again, will have to inspect in the spring for a clean out.							This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017
CD61	18-033	11/19/2018	Cordova	23	Haefner, Charles	Chad Domonoske	A few Sloughs obstructing the ditch.							needs inspection. Holding off work
CD61	18-028	10/22/2018	Cordova	23	Domonoske, Donald & Judy	Tom Jindra	Crossing repair.	zimmerman					\$ 3,443.82	Found that the culvert needs to be replaced.

Le Sueur County Ditch Report: 12/1/18 ■ =New ■ =Closed white=current ■ = In Review

CD61	16-013	9/20/2016	Cordova	23	THEIS,JOHN L & CANDI L	David Novotny	Find where the tile has been plugged or blown out, repair that area to get water flowing again, were told to get a cost estimate before work could be done	Pat Traxler		3/31/2017		Traxler Thinks the problem is the tile in the easment land on the McGillen land. Will have to look into it in the future. Waiting on invoice!
CD61	17-021	42846	Cordova	23	McGILLEN,JOHN E & PAMEL	David Novotny	Tile Holding back water. Needs to be replaced or fixed.					having ISG make an engineering report for the county to replace couy tile.
CD61	17-046	9/11/2017	Cordova	23	McGILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.					Did inspection waiting until after meeting to do work.
CD63	18-004	5/3/2018	Montgomery	36	James Fisher	James fisher	Two culverts, one located on 99 and on located on the fisher land with logs blocking it.					Land owner was concerned about being flooded out by the culvert on 99 that was put in a few years ago. (Found info, Working with HWY DPT)
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.					needs inspection. Holding off work
CD64	18-020	7/27/2018	Cordova	21	DNR Real Estate MGT	Kolander, Leroy	Culvert underwater on highway 11	Selly		7/30/2018		found a beaver dam holding back about 3 ft of water.
CD64	18-031	11/15/2018	Cordova	26	Zimprich, Joseph	Marvin Novotny	ditch clean out.	Zimmerman				Sediment and grass blocking up tile.
CD64	17-053	12/13/2017	Cordova	20	Chadderdon, Orbbe	Norman Schmidt	Beaver dams blocking up ditch					I have ran parts of this ditch and could not find any dams. I will run the ditch this spring.
CD68	18-027	10/1/2018	Cordova	27	Marvin Novotny	Marvin Novotny	Slough	Zimmerman			\$ 360.00	Slough cleaned up.
CD70	18-024	9/14/2018	Tyrone	10	Loewe,Adam	Loewe,Adam	Ditch Abandonment					Did a site check to see if anyone else is benefiting.
JD1 Scott	18-032	11/19/2018	Tyrone	9	Felmlee,Judith ann	Lyle Felmlee	Two sloughs take outlet tile into ditch.					Need to find contractor
JD1 Scott	18-011	6/6/2018	Tyrone	4	Butchel, Ron	Butchel, Ron	Spoils left from previous cleanout has never been spread	Selly				Spoils have been spread.
JD1 Scott	18-005	5/3/2018	Tyrone	2	Kessler, William	Kessler, William	Ersion and sloughing and undercutting.					Looks like his tile might be cause some of his problem on the sloughing part, the ditch bank is mud mid way up next to the tile. Once he fixes his tile we will repair the ditch.

Le Sueur County Ditch Report: 12/1/18 ■ =New ■ =Closed white=current ■ = In Review

JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out							Needs inspection this spring.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.							needs action.
JD15 BE	17-008	2/16/2017	Washington	14	MCCARTHY,JAMES R	Mark Krenik	ditch clean out.	zimmerman	5500				\$ 5,310.00	was cleaned and spoiles spread!

■ = New inquiries within the last 2 months that have not been looked into.

■ = Closed projects that have been inspected and paid for work done.

White= projects that are in progress, they are currently being worked on and still have issue that need to be done.

■ = Projects that are in review, they are projects that have to be looked into or are being set aside for future work.