



Le Sueur County, MN

Tuesday, February 5, 2019

Board Meeting

Item 3

9:10 a.m. Nik Kadel, Ditch Specialist (10 min)

1. County Ditch Update

Staff Contact:

Le Sueur County Ditch Report: 2/1/19 ■ =New ■ =Closed ■ =current ■ = In Review

| Drainage | DB Repair # | Date Received | Township | Section | Landowner | Person Requesting Repair | Problem/Proposed Work | Contractor | Cost Estimate | Start Date | Project complete Date | Final Bill Invoice | Notes |
|----------|-------------|---------------|------------|---------|----------------------------|--------------------------|--|-----------------------|---------------|------------|-----------------------|--------------------|---|
| CD6 | 18-026 | 10/1/2018 | Montgomery | 18 | Rynda,William | Richard Kuckaka | Beaver Dams | selly/ Shane Steven's | | | | \$ 2,120.00 | beaver have been trapped and dams cleared. |
| CD16 | 16-037 | 11/1/2016 | Montgomery | 18 | TRINKA,BETTY A | | Culvert is failing, needs field review. | | | | | | Culvert needs cleaning around it |
| CD16 | 16-040 | 11/3/2016 | Lexington | 13 | NYTES,JAMES L & RUTH A | | clean out to the lake. Need DNR permits to proceed. Water control structure? | | | | | | waiting on DNR water permit |
| CD16 | 16-041 | 11/3/2016 | Montgomery | 18 | TRINKA,BETTY A | | clean out, need DNR permits, control structure? | selly? | 20566.4 | | | | Starting meetings with DNR!!!! |
| CD21 | 16-007 | 4/25/2016 | Lexington | 28 | | Joe Schloesser | washing out next to culvert in driveway | | | | | | Sent letters, no response |
| CD23 | 18-025 | 9/21/2018 | Lexington | 35 | Goettl, Robert & Lori A | Goettl, Robert & Lori A | Beaver dams and beaver problems. | selly/ Shane Steven's | | | | \$ 1,270.00 | We have a trapper out ther along the ditch now. |
| CD23 | 16-024 | 9/29/2016 | Lexington | 20 | WIELAND,ROBERT A & CYNTHIA | | washouts due to heavy rain. side inlets? ditch plugged | | | | | | Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed. |
| CD23 | 16-044 | 11/14/2016 | | | | Don Westerman | Don Westerman wants the outlet structure for mareks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17. | | | | | | drop inlet structure needs replacment. |
| CD29 | 18-035 | 10/1/2018 | Derrynane | 9 | O'connell,James J | O'connell, Mike | Replace all tile on his property. | | | | | | This needs a to be discussed about replaceing whole tile line and have ISG take a look. |
| CD29 | 18-013 | 6/11/2018 | Derrynane | 9 | Stuedemann, Kevin | Stuedmann, Kevin | Crossing repair. | | | | | | wanted to have their own contractor do the work. Have not heard anything from them since. |
| CD31 | 17-052 | 12/12/2017 | Derrynane | 13 | Hoefs, Johns J | Dennis Dietz | Water not flowing through | | | | | | Needs DNR permit to clean through public waters. |
| CD31 | 16-055 | 42709 | derrynane | | JAHN,BRIAN C FAMILY LP | john Widmer | where 31 and 44 meet is clogged with grass. | | | | | | Needs DNR permit to clean through public waters. Found Culvert in Ditch need to more information. |
| CD34 | 17-037 | 12/1/2018 | Sharon | 11 | Dale Tiede | Dale Tiede | Sloughs blocking drainage | Selly | | 12/1/2018 | 12/10/2018 | \$ 750.00 | Couple Sloughs cleaned |
| CD34 | 18-036 | 43430 | Sharon | 2 | Erkel Floyed | Erkel Floyed | Culvert and crossing failing | Selly | | 12/15/2018 | | | Culvert ordered |

Le Sueur County Ditch Report: 2/1/19 =New =Closed white=current = In Review

| | | | | | | | | | | | | | |
|------|--------|------------|------------|----|--------------------------|--------------------------|---|-----------------------|-------|--|--|-------------|---|
| JD38 | 18-006 | 5/4/2018 | Kilkenny | 25 | Houser,Terry W & Bev E | Jim Hebel | Erosion from public waters coming into the county ditch. | | | | | | Going to get some second opinions before we start repiaring ditch. |
| JD38 | 17-054 | 12/21/2017 | Kilkenny | 36 | Miller, Jerome A | Kenneth Wetzel | Need elevation shots on a culvert, Landowner believes culvert is too high. | | | | | | Need to get elevation shots! |
| CD40 | 16-061 | 42725 | Montgomery | 22 | BAUER,LEROY O & BONNIE | BAUER,LEROY O & B | LO stopped in saying lots of sloughing and erosion along his land and further along the ditch | | | | | | Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested. |
| CD40 | 17-004 | 1/12/2017 | Montgomery | 26 | KORBEL,DALE & ALICIA | Dan Gregor | Banks are sloughing from excess rains and water | | | | | | Need to site inspection for work |
| CD40 | 16-014 | 9/21/2016 | Montgomery | 28 | KRAUTKREMER,DENNIS | | Ditch has been cleaned out and install a 30' culvert | Havel | | | | | Land was too wet to finish cleaning by havel. |
| CD41 | 17-043 | 1/24/2017 | Lexington | 30 | Beer, George | Jerry Cooney | Tile failing, Water siting in the field not draining in the culvert. | | | | | | Petition was put in! |
| CD43 | 17-007 | 2/3/2017 | Lexington | 21 | MORAVEC,JACQUELYN M | | water not being able to get into Tyler lake | | | | | | Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake. |
| CD44 | 16-035 | 10/20/2016 | Lanesburgh | 20 | TIEDE,RUSTY & NANCY | Rusty Tiede | Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream. | | | | | | CD 44 needs inspection for a few problems |
| CD44 | 16-054 | 11/30/2016 | Lanesburgh | 7 | JAHN,BRIAN C FAMILY LP | John Widmer | plugged with grass at the point where 31 and 44 meet up. | | | | | | Was inspected, needs a DNR permit to be filled out to be cleaned. |
| CD45 | 18-029 | 11/1/2018 | Lexington | 2 | Miller,Jeff | Dale Tiede | Beaver Dam | selly/ Shane Steven's | selly | | | \$ 2,630.00 | Have a Trapper out there and cleared the Dam. |
| CD45 | 18-021 | 8/7/2018 | Derrynane | 27 | Wacker,Mark | Tom Binzick | Culvert washing out. | Aufderhar | | | | \$ 875.00 | Culvert was replaced, waiting on payment from LO. |
| CD45 | 17-022 | 42851 | Lexington | 1 | pelant, joseph & Barb | Mark Jindra | Ditch needs cleaning | | | | | | Needs another check jan. 2019 |
| CD58 | 18-030 | 11/15/2018 | Cleveland | 29 | Struck, Gerald | Lynn Loeffler | Debri in culvert holding back water. | | | | | | Found a few rocks, looks like culvert will have to be replace. Its starting to rust through. |
| CD59 | 16-017 | 9/23/2016 | Elysian | 3 | Domonoske, Donald & Judy | Domonoske, Doanld & Judy | Asked about this same are again, will have to inspect in the spring for a clean out. | | | | | | This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017 |

Le Sueur County Ditch Report: 2/1/19 =New =Closed white=current = In Review

| | | | | | | | | | | | | | | |
|-----------|--------|------------|------------|----|----------------------------|------------------|---|-----------|--|------------|-----------|-------------|--|---|
| CD59 | 18-034 | 11/19/2018 | Elysian | 11 | quast, milo & vivian | Chad Domonoske | Big slough/ slide going into the ditch | | | | | | | Will fix this spring. |
| CD61 | 18-033 | 11/19/2018 | Cordova | 23 | Haefner, Charles | Chad Domonoske | A few Sloughs obstructing the sitch. | | | | | | | needs inspection. Holding off work |
| CD61 | 18-028 | 10/22/2018 | Cordova | 23 | Domonoske, Donald & Judy | Tom Jindra | Crossing repair. | zimmerman | | 10/26/2018 | 11/7/2018 | \$ 3,443.82 | Found that the culvert needs to be replaced. | |
| CD61 | 17-021 | 42846 | Cordova | 23 | McgILLEN,JOHN E & PAMELA K | David Novotny | Tile Holding back water. Needs to be replaced or fixed. | | | | | | | waiting on improvement process. |
| CD61 | 17-046 | 9/11/2017 | Cordova | 23 | McgILLEN,JOHN E & PAMELA K | david Novotny | Clean open ditch for fall. | | | | | | | Did inspection waiting until after meeting to do work. |
| CD63 | 18-004 | 5/3/2018 | Montgomery | 36 | James Fisher | James fisher | Two culverts, one located on 99 and on located on the fisher land with logs blocking it. | | | | | | | Land owner was concerned about being flooded out by the culvert on 99 that was put in a few years ago. (Found info, Working with HWY DPT) |
| CD63 | 17-009 | 2017-15-3 | Montgomery | 35 | Trcka, Steve & Theresa | Mark Chicoine | Needs inspections for cleaning, there is sloughing. | | | | | | | needs inspection. Holding off work |
| CD64 | 18-031 | 11/15/2018 | Cordova | 26 | Zimprich, Joseph | Marvin Novotny | ditch clean out. | Zimmerman | | 11/15/2018 | 12/4/2018 | \$ 1,935.00 | Sediment and grass blocking up tile. | |
| CD64 | 17-053 | 12/13/2017 | Cordova | 20 | Chadderdon, Orbbe | Norman Schmidt | Beaver dams blocking up ditch | | | | | | | I have ran parts of this ditch and could not find any dams. I will run the ditch this spring. |
| CD70 | 18-024 | 9/14/2018 | Tyrone | 10 | Loewe,Adam | Loewe,Adam | Ditch Abandonment | | | | | | | Did a site check to see if anyone else is benifiting. |
| JD1 Scott | 18-032 | 11/19/2018 | Tyrone | 9 | Felmlee,Judith ann | Lyle Felmlee | Two sloughs take outlet tile into ditch. | | | | | | | Need to find contractor |
| JD1 Scott | 18-005 | 5/3/2018 | Tyrone | 2 | Kessler, William | Kessler, William | Ersion and sloughing and undercutting. | | | | | | | Looks like his tile might be cause some of his problem on the sloughing part, the ditch bank is mud mid way up next to the tile. Once he fixes his tile we will repair the ditch. |
| JD4 SCOTT | 16-058 | 12/12/2016 | Tyrone | 1 | LINDEMAN,LLOYD | Lyle Wagner | Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out | | | | | | | Needs inspection this spring. |
| JD5 RICE | 17-002 | 1/3/2017 | Kilkenny | 10 | SCHULTZ,JERRY L | ken kline | In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area. | | | | | | | needs action. |