



---

# **Le Sueur County, MN**

**Tuesday, April 2, 2019**

**Board Meeting**

## **Item 3**

**9:10 a.m. Nik Kadel, Ditch Specialist (10 min)**

*RE: County Ditches Update*

Staff Contact:

Drainage	DB Repair #	Date Received	Township	Section	Landowner	Person Requesting Repair	Problem/Proposed Work	Contractor	Cost Estimate	Start Date	Project complete Date	Final Bill Invoice	Notes
CD6	18-026	10/1/2018	Montgomery	18	Rynda,William	Richard Kuckaka	Beaver Dams	selly/ Shane Steven's				\$ 2,120.00	beaver have been trapped and dams cleared.
CD16	16-037	11/1/2016	Montgomery	18	TRINKA,BETTY A		Culvert is failing, needs field review.						Culvert needs cleaning around it
CD16	16-040	11/3/2016	Lexington	13	NYTES,JAMES L & RUTH A		clean out to the lake. Need DNR permits to proceed. Water control structure?						waiting on DNR water permit
CD16	16-041	11/3/2016	Montgomery	18	TRINKA,BETTY A		clean out, need DNR permits, control structure?	selly?	20566.4				Starting meetings with DNR!!!!
CD21	16-007	4/25/2016	Lexington	28		Joe Schloesser	washing out next to culvert in driveway						Sent letters, no response
CD23	18-025	9/21/2018	Lexington	35	Goettl, Robert & Lori A	Goettl, Robert & Lori A	Beaver dams and beaver problems.	selly/ Shane Steven's				\$ 1,270.00	We have a trapper out ther along the ditch now.
CD23	16-024	9/29/2016	Lexington	20	WIELAND,ROBERT A & CYNTHIA		washouts due to heavy rain. side inlets? ditch plugged						Did a ditch inspection on about half the ditch. It's going to need a lot of work and a redetermination. Having a meeting with board about how to proceed.
CD23	16-044	11/14/2016				Don Westerman	Don Westerman wants the outlet structure for mareks lake repaired before any ditch clean out takes place. Site needs to be visited and photos taken winter of 2016-17.						drop inlet structure needs replacment.
CD29	18-035	10/1/2018	Derrynane	9	O'connell,James J	O'connell, Mike	Replace all tile on his property.						This needs a to be discussed about replaceing whole tile line and have ISG take a look.
CD29	18-013	6/11/2018	Derrynane	9	Stuedemann, Kevin	Stuedmann, Kevin	Crossing repair.						wanted to have their own contractor do the work. Have not heard anything from them since.
CD31	17-052	12/12/2017	Derrynane	13	Hoefs, Johns J	Dennis Dietz	Water not flowing through						Needs DNR permit to clean through public waters.
CD31	16-055	42709	derrynane		JAHN,BRIAN C FAMILY LP	john Widmer	where 31 and 44 meet is clogged with grass.						Needs DNR permit to clean through public waters. Found Culvert in Ditch need to more information.
CD34	18-036	43430	Sharon	2	Erkel Floyed	Erkel Floyed	Culvert and crossing failing	Selly		12/15/2018			Culvert ordered
CD37	19-001	3/27/2019	Kasota	1	Michael Stoffel	Loren Stoffel	Crossing washed out.	selly					Culvert needs to be reset and add more clay with rip rap.

Le Sueur County Ditch Report: 4/1/19      =New      =Closed    white=current      = In Review

JD38	18-006	5/4/2018	Kilkenny	25	Houser,Terry W & Bev E	Jim Hebel	Erosion from public waters coming into the county ditch.						Going to get some second opinions before we start repiaring ditch.
JD38	17-054	12/21/2017	Kilkenny	36	Miller, Jerome A	Kenneth Wetzel	Need elevation shots on a culvert, Landowner believes culvert is too high.						Need to get elevation shots!
CD40	16-061	42725	Montgomery	22	BAUER,LEROY O & BONNIE	BAUER,LEROY O & B	LO stopped in saying lots of sloughing and erosion along his land and further along the ditch						Land owner spread spoil on his own, I let him know he could be paid for his work but he was not interested.
CD40	17-004	1/12/2017	Montgomery	26	KORBEL,DALE & ALICIA	Dan Gregor	Banks are sloughing from excess rains and water						Need to site inspection for work
CD40	16-014	9/21/2016	Montgomery	28	KRAUTKREMER,DENNIS		Ditch has been cleaned out and install a 30' culvert	Havel					Land was too wet to finish cleaning by havel.
CD41	17-043	1/24/2017	Lexington	30	Beer, George	Jerry Cooney	Tile failing, Water siting in the field not draining in the culvert.						Petition was put in!
CD43	17-007	2/3/2017	Lexington	21	MORAVEC,JACQUELYN M		water not being able to get into Tyler lake						Tyler lake has been looked at waiting on DNR to provide results of OWL. To see if we can clean into the lake.
CD44	16-035	10/20/2016	Lanesburgh	20	TIEDE,RUSTY & NANCY	Rusty Tiede	Rusty Tiede called in to office describing water backing up in Main of CD#44. Problem he said appears to be downstream.						CD 44 needs inspection for a few problems
CD44	16-054	11/30/2016	Lanesburgh	7	JAHN,BRIAN C FAMILY LP	John Widmer	plugged with grass at the point where 31 and 44 meet up.						Was inspected, needs a DNR permit to be filled out to be cleaned.
CD45	17-022	42851	Lexington	1	pelant, joseph & Barb	Mark Jindra	Ditch needs cleaning						Needs another check jan. 2019
CD54	19-003	3/26/2019	Lanesburgh	34	Franek, Jeffrey	Deb Anger	Water backing up on to property. Not draining.						Water is draining very slowly. Land owners are getting nervous.
CD58	18-030	11/15/2018	Cleveland	29	Struck, Gerald	Lynn Loeffler	Debri in culvert holding back water.						Found a few rocks, looks like culvert will have to be replace. Its starting to rust through.
CD59	16-017	9/23/2016	Elysian	3	Domonoske, Donald & Judy	Domonoske, Doanld & Judy	Asked about this same are again, will have to inspect in the spring for a clean out.						This stretch was attempted last year but it was too wet. Land owner asked for it to be looked at again. 10/2017
CD59	18-034	11/19/2018	Elysian	11	quast, milo & vivian	Chad Domonoske	Big slough/ slide going into the ditch						Will fix this spring.
CD61	18-033	11/19/2018	Cordova	23	Haefner, Charles	Chad Domonoske	A few Sloughs obstructing the sitch.						needs inspection. Holding off work

CD61	17-021	42846	Cordova	23	McGILLEN,JOHN E & PAMELA K	David Novotny	Tile Holding back water. Needs to be replaced or fixed.						waiting on improvement process.
CD61	17-046	9/11/2017	Cordova	23	McGILLEN,JOHN E & PAMELA K	david Novotny	Clean open ditch for fall.						Did inspection waiting until after meeting to do work.
CD63	18-004	5/3/2018	Montgomery	36	James Fisher	James fisher	Two culverts, one located on 99 and on located on the fisher land with logs blocking it.						Land owner was concerned about being flooded out by the culvert on 99 that was put in a few years ago. (Found info, Working with HWY DPT)
CD63	17-009	2017-15-3	Montgomery	35	Trcka, Steve & Theresa	Mark Chicoine	Needs inspections for cleaning, there is sloughing.						needs inspection. Holding off work
CD70	18-024	9/14/2018	Tyrone	10	Loewe,Adam	Loewe,Adam	Ditch Abandonment						Did a site check to see if anyone else is benefiting.
JD1 Scott	19-002	3/27/2019	Tyrone	9	Woestehoff, David		Crossing washing out.	selly					Culvert washing out from one side. Needs riprap.
JD1 Scott	18-032	11/19/2018	Tyrone	9	Felmllee,Judith ann	Lyle Felmllee	Two sloughs take outlet tile into ditch.						Need to find contractor
JD1 Scott	18-005	5/3/2018	Tyrone	2	Kessler, William	Kessler, William	Ersion and sloughing and undercutting.						Looks like his tile might be cause some of his problem on the sloughing part, the ditch bank is mud mid way up next to the tile. Once he fixes his tile we will repair the ditch.
JD4 SCOTT	16-058	12/12/2016	Tyrone	1	LINDEMAN,LLOYD	Lyle Wagner	Lyle wagner stopped in saying that he and a few neighbors think the ditch will have to be cleaned out						Needs inspection this spring.
JD5 RICE	17-002	1/3/2017	Kilkenny	10	SCHULTZ,JERRY L	ken kline	In the Cannon River section of kilkenny, below Dora. Need to ok with DNR and Knish. the Bill should be split equally between JD5, CD40, CD57 and CD63- these are backed up by beaver dams with in the area.						needs action.